

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

Ram Ratan Ram.

2 Name of Block :-

Lo31 to Hariya tola. chansa.

3 Name of Road :-

Lo31 to Hariya tola.

A. For Road

1 Damage Location/Chainage :- 0.380km-0.450km, 0.700km to 0.800km, 0.860km to 0.890km,
1.080km - 1.250km

2 Damage Length :- 0.500km

3 Nature of damage :- Road crust.

4 Details of Restoration Works :-

i Material being used in Restoration works:- B/c bags, bamboo etc.

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :- 0.500km

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-


4 Details of Restoration Works :-

i Material being used in Restoration works:-


ii Equipments/Tools being used in Restoration works :-


iii Procedure taken up in Restoration works :-

iv Restored Length :-


27/11/2020
JE


27/11/2020
AE


27/11/2020
EE


Signature
(Name of inspector)

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:			LO 31 to		NARAIYA
			TOLA.		
Agency				:	
Head				:	FDR
Total length of road				:	1.270km
Flood effected of road				:	0.560km
Record Entry:					

① Supplying fitting and
 fixing in position split
 bamboo woven chanchang.

 For 70.00m.

Pile:- $137.00 \times 5.50 = 753.50m$

Runner: $320.5 \times 70.00 = 22435.00m$



963.50m

Total No of bamboo = $\frac{963.50}{6} = 160.58$

② Labour for cutting 62mm
 to 75mm dia bamboo piles
 in line and making
 shoe, so complete. --- 4;

Pile: $1 \times 753.50 = 753.50m$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Labour for cutting					
62mm to 75mm dia bamboo runner in size 1/1					
Runner:	3	70.00	=	210.00m.	
④ Supplying of longitudinal cloth					
					= 6kg
⑤ Labour fitting empty canvas bag with local sand, stitching the bags and placing 1/1					
	3	140	X 6	=	2520
Bethelidol		2520	X 2	=	5040.00m
 28/11/21  28/11/21					
Record Entry:					
For 55.00m length.					
① Supplying, fitting and fixing with in position spot Bamboo woven chequering 1/1					
Pile:-	106.00	m X	5.50	=	583.00m
Runner:-	3 Nos	X	55	=	165.00m
					<u>748.00</u>
No. of bamboo:					126 Nos
② Labour for cutting 62mm to 75mm dia bamboo piles in size and making 1/1					
	1	106	X	583	= 583.00m

Continuation

Scanned with CamScanner