

FDR-2020-21

N/w - Basgarha Parbatla To Jothgovind.
Schedule XLV Form N.134.

P.W.D.

Naugachhiya.

DIVISION

Jemilepur.

SUB DIVISION

MEASUREMENT BOOK-570

प्रमाणित किया जाता है कि
भाषी पुस्त संख्या 570 में नशीन
मुद्रित कुल 100 (एक सौ) पेज
अंकित हैं। यह भाषी पुस्त श्री
अकबरा कुतार सहायक अभियंता
कार्य अंतर प्रमंडल - ईमानापुर
के नाम FOR भोजनार्थों के कार्य
हेतु निर्गत किया जाता है।

12/11/2020

Executive Engineer

R.W.D. W.D. Narsaria

12/11/2020

Schedule XLV Form No. 134

.....DIVISION

.....SUB-DIVISION

MEASUREMENT BOOK

Name of Office.....

Date of first entry.....

Date of last entry.....

Name of work - 1

Situation of work -

Agency by which work is executed -

Date of measurement.

No. and date of agreement

(These four lines should be repeated and the commencement of the measurement relating to each work.)

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
Name of work - Temporary Retention work in Bargaha Parbatta to Jothgoring Road.					
Block - Ismipur					
Agency - Departmental.					
Authority - Executive Engineer R.W.D. work Division Nalgachhiga.					

Record Entry.

Date - 20/08/2020

① Providing Sand bag with sand and labour including Carriage Laying filling etc all complete

Job - do -

Along Laxmipur village. Both side.

$$2 \times 20.0 \times \frac{2.0 + 1.0}{2} \times 1.0 = 60.0 m^3$$

Ch - 4000 to 6000 m (4h.3)

$$10 \times 3.0 \times 1.50 \times 1.20 = 54.0 m^3$$

$$5 \times 2.0 \times 1.0 \times 0.90 = 9.0 m^3$$

123.0 m³

(Continuation) or, 3618 bag

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
② Providing Bricks bats including spreading laying hand packing and compacting with 6.3 hammer - do -					
Neon Laxmipur village, Part - I (CH - 0 to 150 m)					
1x27.0 x 4.0 x 0.60 =					64.80 m ³
1x30.0 x 3.0 x 0.30 =					27.00 m ³
1x10.0 x 3.0 x 0.30 =					9.0 m ³
					Total = 100.80 m ³

Wish.
20/08/2020
J.E

Wish.
20/8/20

Record Entry.

Date - 21/8/2020

① Providing F. bag with sand and labour including cartage laying filling - do.

Near Laxmipur village.

L.H.S - 1x20 x 1.50 x 1.0 = 30.0 m³R.H.S - 1x25 x 1.50 x 0.90 = 33.75 m³63.75 m³

or 1875 bags

Particulars	Details of actual measurement				Contents or area
	No.	L	B	D	
Record Entry.					
Date -	12/09/2020				
① Providing Brick bats including spreading					
laying hand picking and compacting with					
C.I hammer - also -					
Near Karpur village.					
1x 30.0 x 4.0 x 0.90 =					108.0m ³
1x 35.0 x 3.50 x 0.60 =					73.50m ³
CH-7000 to 9000 m					
1x 5x 0.50 x 0.40 =					1.0m ³
1x 6x 0.50 x 1.00 =					3.0m ³
1x 3x 1.0 x 1.0 =					3.0m ³
1x 4x 1.50 x 1.50 =					9.0m ³
1x 5x 2.0 x 1.20 =					12.0m ³
4x 3.0x 0.50 x 1.30 =					7.80m ³
5x 2.0x $\frac{1.0+0.75}{2}$ x 1.10 =					9.68m ³
4x 3.0x 1.50 x 1.30 =					23.40m ³
1x 6.0x 1.50 x 1.40 =					12.60m ³
1x 7.0x 1.50 x 1.20 =					12.60m ³
4x 5.0x 1.0 x 1.20 =					24.0m ³
1x 20.0x $\frac{2.0+1.0}{2}$ x 0.50 =					15.0m ³
5x 2.0x 0.50 x 0.80 =					1.50m ³
Total =					316.08m ³
Ukgd.					
12/09/2020					
J.E					

(Continuation)

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
	Final Bill				
Name of work -	Temporary Restoration				
	work in Bangarha Barabatta				
	to Jethgoring Road.				
Block -	Imilepur.				
Agency -	Departmental				
Authority -	Executive Engineer.				
	R.M.D. work Division				
	Naugachhija.				
Date -	15/01/2021				

ABSTRACT OF COST

①	Plv E.C bag with				
	sand and labour				
	including cartage				
	laying filling				
	— or —				
	same qty wide time				
3618 bag	9 item - 1 A Page - 1				
	same qty wide time				
1875 bag	9 item - 1 A Page - 2				
5493 bag	@ 31.22/bag - Rs 171491.22				
②	Providing Brick bats				
	including spreading				
	laying hand packing				

(Continuation)

Rs 171491.22

Inspection Report For Flood Damage Work

Date :- 22/02/2021

1. Name of PIU - Executive Engineer, R.W.D. Div - Naugachia
2. Name of Block/Road :- Bargaha Parbatia to Jethgerind.
Block - Ismailpur
PK No - BR-06R-049
- A. For Road
 1. Damage location/Chainage 7000 - 9500 m / 4000 - 6000 m, Part-II, Ch - 0 to 150 m (near Laxmipur village)
 2. Damage length - 75 m, 40 m, 120 m
 3. Nature of Damage. Erosion by Flood water.
 4. Details of Restoration Works
 - (i) Material being used in Restoration Works: local sand, R.C bag & brick bats.
 - (ii) Equipment's/Tools Being used in Restoration Works:
 - (iii) Procedure Taken up in Restoration Works:
 - (iv) Restored Length: 235 m (shoulder / Flank)
- B. For Bridge
 1. Damage Location/Chainage
 2. Damage length
 3. Nature of Damage
 4. Details of Restoration Works
 - (I) Material being used in Restoration Works:
 - (II) Equipment's/Tools Being used in Restoration Works:
 - (III) Procedure Taken up in Restoration Works:
 - (IV) Restored Length:
- C. Requirement of New CD/Bridges
 - (I) Name of Road:
 - (II) Location/Chainage
 - (III) Type of CD Work/Length required

Notes:-

- Upload one Photograph of damaged portion if available
- Attach minimum Two Photograph (during restoration & after restoration) photographs should be Geotags and at Least one Photo be captured in selfie mode.
- Restoration work has been done during flood season, but at present exact measurement can't be possible as per actual work done.

Vingl.
22-02-21
S.B.

Signature of JE/AE/EE

Executive Engineer
R.W.D. W.D., Naugachia

Signature

(Name of Inspector)