

FDR- 2020-21

N/W - MMWSY Chandani Chowk TD Malpur.

Schedule XLV Form N.134.

P.W.D.

Naugachhiya.

DIVISION

Temlepur

SUB DIVISION

---

# MEASUREMENT BOOK

-578

---

संख्या ५२८ ले नवीन प्रौद्योगिकी द्वारा  
१०० (प्रक्रमी) फेम अंतर्गत है १०० लाख  
पुस्तकी अवधें तुलार संबंधित  
अधिकारिता द्वारा अवर भवान-इस्ताना  
के नाम FDR भवनाजी के कार्य से  
निर्मित भिन्न भाग है।

R.W.D.  
Executive Engineer  
R.W.D. W.D. Naupatra  
*R.W.D.*  
27/1/2010

Schedule XLV Form No. 134

DIVISION I

SUB-DIVISION I

MEASUREMENT BOOK

Name of Office.....

Date of first entry.....

Date of last entry.....

Name of work - 1

Situation of work -

Agency by which work is executed -

Date of measurement.

No. and date of agreement.

(These four lines should be repeated and the commencement  
of the measurement relating to each work.)

Particulars	Details of actual measurement				Contents No. L. B. D. or area
	No.	L.	B.	D.	

Name of work - Temporary Restoration

work in MMULS Y chandni

chawki To Malpur.

Length - 0.702 km

Block - Ismailpur.

Agency - Departmental

Authority - R.E, R.W.D, W.B. Division  
Nangarkheda.

Record Entry

Date - 25/08/2020

① Providing bag with

sand and labour

including carriage

Laying filling etc -

Complete job.

CH - 50 m to 105 m

$$1 \times 8.0 \text{ m} \times \frac{2.0 + 10.0}{2} \times 4.50 = 54.0 \text{ m}^3$$

Near Bridge -

$$2 \times 5.0 \times \frac{1.60 + 0.90}{2} \times 0.30 = 3.75 \text{ m}^3$$

$$1 \times 6.0 \times \frac{1.0 + 0.60}{2} \times 0.60 = 2.88 \text{ m}^3$$

$$2 \times 8.0 \times \frac{1.0 + 0.60}{2} \times 3.0 = 38.40 \text{ m}^3$$

$$99.03 \text{ m}^3$$

(Continuation) or, 2912 bags

Sch. XLV- Form No. 134

Sch. XLV- Form No. 134

**(Continuation)**

## Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
					<u>Final Bill</u>
Name of work - Temporary Restoration					
workings man by chandri					
Chaurk to Malpur. (L=0.702 km)					
Block - Ismipur.					
Agency - Departmental					
Authority - E.E. R.W.D. work division					
Nangachhaya.					
Date - 18/01/2021					
<u>ABSTRACT OF COST</u>					
① Providing E.C					
bag with sand					
and labour					
including carriage					
Laying filling					
etc					
complete job					
same at 1/2 rate T.M.B					
93cm - 12 Page - 1					
2912 bags @ 31.22/bag - Rs 90913.00					

②	Providing Bricks
	Batts including
	spreading laying
	hand packing

(Continuation) Rs 90913.00

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
					and Compacting
					— old —
					same qty rideons
125.40m <sup>3</sup>	94 cum	-23	Page -2		
166.0m <sup>3</sup>	94 cum	-13	Page -3		
291.40m <sup>3</sup>	@ 1718.47 m <sup>3</sup>			Rs 500762 = 00	
				Rs 591675 = 00	
Addd M.S.T @ 12%				71 001 = 00	
Add L.G.E.H @ 1%,				59 17 = 00	
Add S.F @ 10%				32 380 = 00	
				Rs 700973 = 00	
W.M. 18/10/21				(Rev) 18/10/21	
S.E.					

R.P no 5 from

Executive Engineer  
R. W. L., W. D. Naugachio

(Continuation)

## Inspection Report For Flood Damage Work

Date :- 22.02.21

1. Name of PIU - Executive Engineer (RWD) work division - Naugachia.
2. Name of Block/Road :- PMBLY chandni chowk TO malpur. Length - 0.702 KM  
A. For Road  
  1. Damage location/Chainage CH. 0.700M
  2. Damage length 147 M
  3. Nature of Damage Erosion by flood water.
  4. Details of Restoration Works
    - (i) Material being used in Restoration Works: local sand, EC bags, Brick bats
    - (ii) Equipment's/Tools Being used in Restoration Works:
    - (iii) Procedure Taken up in Restoration Works:
    - (iv) Restored Length: 147 M (Planned shoulder)
- B. For Bridge
  1. Damage Location/Chainage
  2. Damage length
  3. Nature of Damage
  4. Details of Restoration Works
    - (I) Material being used in Restoration Works:
    - (II) Equipment's/Tools Being used in Restoration Works:
    - (III) Procedure Taken up in Restoration Works:
    - (IV) Restored Length:
- C. Requirement of New CD/Bridges
  - (I) Name of Road:
  - (II) Location/Chainage
  - (III) Type of CD Work/Length required

### Notes:-

- \* Upload one Photograph of damaged portion if available
- \* Attach minimum Two Photograph (during restoration & after restoration) photographs should be Geotags and at Least one Photo be captured in selfie mode.
- \* Restoration work has been done during flood season, but at present exact measurement can't be possible as per actual work done.

22/02/21  
5/8  
Signature of JE/AE/EE  
Executive  
**R. W. D. W. D., Naugachia.**

22/02/21  
Signature  
(Name of inspector)

22/02/21  
A-E  
Signature

22/02/21  
AB