

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Rgon Raton Rgon
2 Name of Block :- Udalchis Lergan
3 Name of Road :- Details of Obstruction for Temporary Restoration
of Road from N.B. Road to Bidin road

A. For Road


- 1 Damage Location/Chainage :- 3.6 km to 4.6 km
2 Damage Length :- 0.2 to 0.3 km
3 Nature of damage :- Road Crest
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-
- } Bhaskar Bhat

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-


JE


AE


EE



Signature
(Name of inspector)

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road - Dredging					
Estimate for Temporary					
Removal of 1000 cu yds					
to Bidding of					
Agency =					
Month = FEB					

Actual length = 4.050 km					
Also after road					
length = 0.120 km					
Reedy Estuary					
14 12.6 x 4.20 x 0.45 = 22.68					
14 10.4 x 4.20 x 0.60 = 25.20					
14 52.4 x (4.5 + 8.5) x 1.8					
2 = 608.40					
<u>Sum</u>					
35.60 x 12.6 x 0.70 = 294.2					
14 10.4 x 4.20 x 0.45 = 18.90					

Continuation

969.18 m³

Part of
2/12/20
KE

25/12/20
AE

Continuation