

Inspection Report for Flood Damage work

Date:-

Name of PIUS :-

R.W.D. Uda Kisungga

Name of Block :-

Puraini

Name of Road :-

PMHsy Khero to Rajik Tola phulobassa

or Road

Damage Location/Chainage :- (0.010 - 0.300) (0.400 - 550) (0.600 - 0.990) (1.100 - 1.200)

Damage Length :- 1.950 km

(1.250 - 2.050)

Nature of damage :- Road Crack

Details of Restoration Works :-

Material being used in Restoration works:- Brick galls, Sand bag, Bamboo

Equipments/Tools being used in Restoration works :-

Procedure taken up in Restoration works :-

Restored Length :-

or Bridge

Damage Location/Chainage :-

Damage Length :-

Nature of damage :-

Details of Restoration Works :-

Material being used in Restoration works:-

Equipments/Tools being used in Restoration works :-


Procedure taken up in Restoration works :-

Restored Length :-


23/11/2020
JE


24/11/2020
AE


24/11/2020
EE


22/11/2021

Signature

(Name of inspector)

ch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Labour for cutting 62 mm to 75 mm dia bamboo piles — — etc					
		218	1.25	⇒	272.50 m
		210	1.25	⇒	262.50 m
		179	1.25	⇒	223.75 m
		179	1.25	⇒	223.75 m
					992.50 m
② 992.50 × 1.25 × 3 =					2322.00 m
③ Labour for billing and fixing 75 mm dia bamboo — — etc					
		10	5	⇒	50.00 m
		12	4	⇒	48.00 m
		5	6	⇒	30.00 m
		12	5	⇒	60.00 m
		5	3	⇒	15.00 m
		2	5	⇒	10.00 m
		35	4	⇒	140.00 m
		25	5	⇒	125.00 m
		8	4	⇒	32.00 m
		15	15	⇒	225.00 m
					735.00 m
④ Supply of bamboo at site — — etc					
1 No. bamboo 6 m				⇒	519.00 m

Continuation

Particulars	Details of actual measurement				Contents of sheet
	No.	L	B	D	
⑤ Labour filling borrow common logs with local sand — — —					
	50 x 5	⇒	150	10	1500
	30 x 5	⇒	150	10	1500
					3000 or 3000
⑥ Labour filling borrow common logs with local sand — — —					
50 x 5 ⇒ 150 10 1500					
30 x 5 ⇒ 150 10 1500					
3000 or 3000					
<u>ESTIMATE OF COST</u>					
① providing & laying artificially — — —					
② T.M.S. — 2.50 — 221.28					
③ 1274.97/m ³ ⇒ 152333.37					
					152333.37
④ Labour for cutting 6.5 mm to 25 mm dia bamboo piles — — —					
T.M.S. — 2.50 — 221.28					
⑤ 41.21/m ⇒ 2201.28					
					2201.28
⑥ Labour for filling having 25 mm dia bamboo — — —					
T.M.S. — 2.50 — 221.28					
⑦ 5.06/m ⇒ 210.24					
					210.24
					2219.10
					2219.10

Continuation

~~1631945.58~~~~1631945.58~~

1680316.49

8. L. No. 1620316. 53

5

900 XLV - Form No. 134

1443780-21
1443780-52

Particulars	Details of actual measurements			Contents of area
	No	L	B	

(4) Supply at site for
cement bags - 25

TRIP - 29 kg - 520 cm

@ 155.68 / m → 20938.00

(5) Labour filling empty
cement bags - 1

TRIP - 4 kg - 370 cm

@ 24.75 / No $\frac{1 \text{ bag}}{25}$ 10425.00

224.75

128720.36

1312.60.00

222602.00

205315.52

128720.36

1312.60.00

222602.00

205315.52

128720.36

1312.60.00

222602.00

205315.52

128720.36

1312.60.00

222602.00

205315.52

128720.36

1312.60.00

222602.00

205315.52

Subtotal
24/01/2021
J.E

Total →

1772273.75

@ 1240.03754 212673.53

@ 1.70 labour cost 27722.73

2002675.81

Say Rs 20,02,675.81

Subtotal
24/01/2021
J.E

At
24/01/2021
At

At
24/01/2021
At

Continuation