

FDR 2020-21

TOL TO BELHI (PMGSY) UNDER FDR

Schedule XLV-Form No. 134

MB NO - 1425

R.W.D WORKS, DTV, SUPAUL **DIVISION**

MARAUNA **SUB-DIVISION**

Measurement Book

प्रमाणित किया जाता है कि इस
 मापदंडिका से कुल 50 (पचास) मशीन
 द्वारा प्रमाणित प्राप्त है जो श्रीमिशनर
 प्रसाद सुन्दर, सहायक मजिस्ट्रेट
 और 31 मशीन मरौदा के नाम
 से निरंतर किया जाता है

कार्यपालक अभियन्ता
 ग्रामीण कार्य विभाग
 कार्य प्रणाली (सुपरीस)

Sch. XLV-Form No. 134

Subaul DIVISION
Marauna SUB-DIVISION

Measurement Book

No. 1425

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

ABSTRACT OF COST

IDR-2020-21

1/2) Providing and
laying brick bats
in damage portion
— as per lit

Qty - 43.20 m^3 vide TMB P-①@ Rs - $1864.35/\text{m}^3$ Rs - 80539.92

Total Rs - 80539.92

Add. Seigniorage Fee (+) Rs - 4592.16Add. GST @ 12% (+) Rs - 9664.79Add. Green @ 1% (+) Rs - 805.39Total Rs - 95602.26

Say Rs - 95602.00

for
18/4/21
for
18/4/21
DRS/M)

Inspection Report for Flood Damage Work

Date:-

1. Name of PIUs :- E.E, RWD, Works Division, Supaul.
2. Name of Block :- Morang
3. Name of Road :- To 1 to Belu

A. For Road

1. Damage Location/Chainage :- 0.886 km
2. Damage Length :- 16 M
3. Nature of Damage :- Due to Flood
4. Details of Restoration Works :-
 - i. Material being used in Restoration works:- Bricks
 - ii. Equipments/Tools being used in Restoration works:- Tractor.
 - iii. Procedure taken up in Restoration works :- Filling
 - iv. Restored Length :- 16 M

B. For Bridge

1. Damage Location/Chainage :-
2. Nature of Damage :-
3. Detail of Restoration Works :-
4. Detail of Restoration Works :-
 - i. Material being used in Restoration works :-
 - ii. Equipments/Tools being used in Restoration work :-
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored Length :-

N/A

JE
30/11/20

AE
30/11/20

EE
30/11/20

signature

Executive Engineer,
(Name of Inspector)
Work Division, Birpur