

✓
FDR. 2020. 21

Schedule XLV Form N.134

P.W.D. N/W. 104-31 To Sadhna Chagan village

NAVGA CHHIVA

DIVISION

RANURA CHOWK

SUB DIVISION

MEASUREMENT BOOK

SSS

Particulars	Details of actual measurement				Contents or area
	No.	L	B	D	
				3R	49.40m ³
CH: 450m to 1000m					
		2x10m	3m	0.30	= 18m ³
		2x8m	2m	0.60	= 19.20m ³
		2x12m	2m	0.60	= 28.80m ³
		2x15m	2m	0.60	= 36m ³
		2x10m	2m	0.60	= 24m ³
		2x8m	3m	0.30	= 14.40m ³
		2x10m	2m	0.30	= 12m ³
		2x5m	3m	0.60	= 18m ³
		2x7m	2m	0.30	= 8.40m ³
		2x8m	2m	0.30	= 9.60m ³
		2x15m	2m	0.30	= 18m ³

		2x10m	2m	0.60	= 24m ³
		2x18m	2m	0.60	= 43.20m ³
		2x15m	2m	0.60	= 36m ³
		1x30m	2m	0.30	= 18m ³
		1x14m	2m	0.30	= 8.40m ³
		1x20m	2m	0.60	= 24m ³

CH: 1030m to 1230m

		2x12m	2.20	0.30	= 15.84m ³
		2x15m	2m	0.30	= 18m ³
		2x18m	2m	0.30	= 21.60m ³
		2x10m	2m	0.30	= 12m ³
		1x5m	2m	0.30	= 3m ³

Total (Qty) = 477.84m³

(Continuation)

Say 14053 Bags

16/12/2020
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग

29/10/20
m

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
					ABSTRACT OF COST.
(5753)					providing sand bag with sand and labor including cartage laying, filling etc all completed job as per specification and direction dtg/
					Same qty note no.
					Page no 2
					14053 bags @ 31.22/End Rs. 438735=00
					Add labor @ 12% - Rs. 52648=00
					Add labor cost @ 1% = 4387=00
					Add S.F. @ 10% - Rs. 6778=00
					Total Rs. = 5,02,548=00
					Any limit Rs. 5,02,500=00
					M/14 28/08/2020 55.
					29/10/20
					20/03/24
					कार्यपालक अभियन्ता
					ग्रामीण कार्य विभाग
					काठ प्रमण्डल नवगछिया

Inspection Report For Flood Damage Work

Date :- 2/03/2021

1. Name of PU - Executive Engineer R.W.D. Work Division Naugachhia.
2. Name of Block/Road :- Rangraichowk / NH-31 To Sadhug ~~Star~~ Chapra village
PKMD No RR-06 R-337
 - A. For Road ✓
 1. Damage location/Chainage CH: 0-75m, 450m-1000m, 1030-1230m
 2. Damage length 43m, 366m 115
 3. Nature of Damage Erosion by flood water
 4. Details of Restoration Works
 - (i) Material being used in Restoration Works: (local sand, E. bags)
 - (ii) Equipment's/Tools Being used in Restoration Works:
 - (iii) Procedure Taken up in Restoration Works:
 - (iv) Restored Length: 524m (flank/shoulder & pot patch)
 - B. For Bridge
 1. Damage Location/Chainage
 2. Damage length
 3. Nature of Damage
 4. Details of Restoration Works
 - (I) Material being used in Restoration Works:
 - (II) Equipment's/Tools Being used in Restoration Works:
 - (III) Procedure Taken up in Restoration Works:
 - (IV) Restored Length:
 - C. Requirement of New CD/Bridges
 - (I) Name of Road:
 - (II) Location/Chainage
 - (III) Type of CD Work/Length required

Notes:-

- Upload one Photograph of damaged portion if available
- Attach minimum Two Photograph (during restoration & after restoration) photographs should be Geotags and at Least one Photo be captured in selfie mode.
- Restoration work has been done during flood season, but at present exact measurement can't be possible as per actual work done.

Signature of JE/AE/EE

Executive Engineer
R. W. D., W. D. Naugachia

Signature
(Name of Inspector)

W.D.
2/3/21
JE

W.D.
2/3/21
AE

W.D.
2/3/21
AE

W.D.
02.03.21
A.E.

W.D.
02/03/21
AE