

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Ram Ratan Ram
2 Name of Block :- Uda Kishturam
3 Name of Road :- ~~Road~~ ~~Detail~~ ~~and~~ ~~Estimated~~ for temporary
Restoration of Road from Mijars to Jotardi

A. For Road

- 1 Damage Location/Chainage :- 0 to 1.00 km, 1.20 km to 2.5, 2.70 to 3.70 km,
4.50 km to 5.50 km, 5.70 to 6.20 km
2 Damage Length :- 4.20 km
3 Nature of damage :- Road cut
4 Details of Restoration Works :- } Brick Bed
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

B. For Bridge

N.A

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works:-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

[Signature]
JE

[Signature]
AE

[Signature]
EE

[Signature]
21/1/2019
Signature
(Name of Inspector)

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Agree of Road - Detailed Estimate for Temporary Repavement of Road from May 1949 to July					
Agency					
Actual Length = 6.230 km					
Width of Road					
Road width = 4.210 km					
Dipping of Road bed on affected Road - also - approx.					
Measurement Details					
24/5.60 x 1.8 x 0.25 = 10.80 m ³					
24/8.60 x 2.0 x 0.20 = 6.4 m ³					
24/9.80 x 1.0 x 0.25 = 8.36					
14/25.60 x 1.5 x 0.25 = 7.50					
14/16.60 x 1.3 x 0.25 = 5.20					
64/3.60 x 1.1 x 0.25 = 3.96					
24/2.80 x 1.0 x 0.20 = 4.80					
54/6.60 x 2.0 x 0.25 = 12.5					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	1.	a.	D.	
24/6.6m	1.6m	0.2			6.4m
14/8.6m	3.4m	0.2			4.8
24/2.4m	2.4m	0.2			6.72
14/4.6m	3.8m	0.2			2.50
14/6.6m	3.4m	0.2			3.60
24/1.6m	1.6m	0.3			10.80
14/1.4m	1.4m	0.2			3.92
14/1.8m	1.6m	0.25			7.20
44/4.6m	2.6m	0.25			9.60
14/10.6m	2.8m	0.25			5.6

14/1.6m	1.6m	0.25			4.75
14/1.5m	1.6m	0.2			4.80
24/1.9m	1.2m	0.25			8.4
24/2.4m	2.6m	0.2			1.60m
14/2.5m	1.2m	0.25			6.75
94/6.4m	1.8m	0.2			5.40
14/12.6m	2.4m	0.2			5.76

Total 157.02m

Received by
 (Signature) of Owner
 (Signature) of Receiver

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
portion of specification					
— do — defects &					
penetration of E/T					
842.65x3.4x0.20=					9.60
1412.0x1.56x0.20=					3.60
1418.4x4.7x0.30=					7.56
2412.0x1.58x0.20=					7.20
248.6x1.4x0.20=					4.48
1414.0x1.60x0.20=					4.48
444.6x3.4x0.25=					12.60

2415.0x1.10x0.30=					9.90
2425.0x1.10x0.25=					13.75
1412.0x2.60x0.25=					6.60
248.6x3.0x0.20=					9.60
1413.6x3.6x0.20=					11.70
2414.4x1.50x0.20=					8.40
1412.0x1.60x0.20=					3.84
1415.0x2.50x0.20=					7.50
1412.0x2.10x0.20=					5.04
248.6x2.60x0.20=					9.60
1412.0x1.20x0.20=					2.88
1415.0x1.50x0.25=					5.62
148.6x2.10x0.40=					4.20
					146.75

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST					
Logging and moving of					
Brick work on					
effect of Room					
portion as per					
specimen - - -					
- - -					
Qty will be for (8)					
Qty = 971.14 m ³					

Continuation

