

FDR-2020-21

T01 (PMD) T0PARSAUNT WITH (INDS. HIL Bridge L-100-2224)
UNDER W.B.

Schedule XLV-Form No. 134

MBNO 1423

R.M.D. MORIS, DIV. SUPAUL DIVISION

MARAJUNA SUB-DIVISION

Measurement Book

ଅନୁରୋଧ କରୁଛି ଯେ
ପ୍ରାୟ ୫୦ ଗ୍ରାମ (୧୫୦ ଫୁଟ)
ପ୍ରାୟ ୫୦ ଗ୍ରାମ (୧୫୦ ଫୁଟ) ପ୍ରାୟ
୫୦ ଗ୍ରାମ (୧୫୦ ଫୁଟ) ପ୍ରାୟ
୫୦ ଗ୍ରାମ (୧୫୦ ଫୁଟ) ପ୍ରାୟ
୫୦ ଗ୍ରାମ (୧୫୦ ଫୁଟ) ପ୍ରାୟ

ଶ୍ରୀ ଶ୍ରୀ
କାର୍ଯ୍ୟକାରୀ ଶାସ୍ତ୍ରୀ
ଶାସ୍ତ୍ରୀ କାର୍ଯ୍ୟ ବିଭାଗ
କାର୍ଯ୍ୟକାରୀ (୧୫୦ ଫୁଟ)

Sch. XLV-Form No. 134

Supaul DIVISION
Moraung SUB-DIVISION

Measurement Book

No. 1423

FDR

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Restoration of road for					
To (PMD) To par					
Survey with (0.1408					
Hill Bridge, L-100, 2004)					
Under FDR.					
Agency - Departmental					
Authority - E.E, RWD, W&S					
Division, Superint					
Date of measurement - 02/09/2003					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Sand filling in ditch & breach					
Between of road —					
a/c 61					
Ch-0.1250 —	2	25.0m	2.50	0.60	75.0m ³
2) Filling and laying					
Brick Sars —					
a/c 61					
Ch-0.1250 —	1	4.0m	3.50m	0.90	12.60m ³
Ch-0.1250 —	1	25.0m	2.0m	0.45	22.50m ³
	1	25.0m	2.0m	0.45	22.50m ³
Ch-1.7010 —	1	12.0m	3.0m	0.20	7.20m ³

$$1 \times 4.0m \times 3.0m \times 0.30 = 3.60m^3$$

$$1 \times 11.0m \times 2.10m \times 0.50m = 6.93m^3$$

$$1 \times 12.0m \times 2.50m \times 0.45m = 13.50m^3$$

$$44 = 88.830m^3$$

Done
02/9/20
JCH

Done
02/9/20
JCH

Done
02/9/20
JCH

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

ABSTRACT OF COST

FDR-2020-21

1/2) Sand filling in
ditch & breach

Particulars — as

per cu ft

Qty - 75 m³ vide TMB page (2)@ Rs 554.03/m³ Rs - 41552.252/2) Providing and laying
brick bats in dam

age Particulars —

as per Bill

Qty - 88.83 m³ vide TMB page (2)@ Rs - 1864.35/m³ Rs - 165610.21

Total Rs - 207162.46

Add. Seigniorage Fee @ 1% Rs - 10719.28

Add. CST @ 12% (1) Rs - 24859.49

Add. L. Cen @ 1% (1) Rs - 2071.62

Total Rs - 2,44,812.85

Say Rs - 244813/-

June
 18/4/21
 JS

18/4/21
 (Signature)

Inspection Report for Flood Damage Work

Date:-

1. Name of PUs :- ETE, RUD MUDS Division, Supaul.
2. Name of Block :- Manqum
3. Name of Road :- To to Pasaum, with (1000 ft. L of 1-1000. 12.25 m (width))

A. For Road

1. Damage Location/Chainage :- 0.120 km, 0.125 km, 0.170 km
2. Damage Length :- 93 m
3. Nature of Damage :- Due to Flood.
4. Details of Restoration Works :-
 - i. Material being used in Restoration works:- Bricks, sand, and fuel
 - ii. Equipments/Tools being used in Restoration works :- JCB, Tractor
 - iii. Procedure taken up in Restoration works :- Filling
 - iv. Restored Length :- 93 m

B. For Bridge

1. Damage Location/Chainage :-
2. Nature of Damage :-
3. Detail of Restoration Works :-
4. Detail of Restoration Works :-
 - i. Material being used in Restoration works :-
 - ii. Equipments/Tools being used in Restoration work :-
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored Length :-

JE Shree
AE Shree
EE Shree

signature
Executive Engineer
Rural Development
Work Division, Birpur

10/10/11