

Inspection Report for Flood Damage work

Date:-

Name of PIUS :-

Name of Block :-

Name of Road :-

Karm Ratan Ram

Wool pang

Wool pang playnagar Kharan

For Road

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

1.60 km

Local cut

} Brick Ball, Local Sand

B. For Bridge

MA

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-


iii Procedure taken up in Restoration works :-

iv Restored Length :-


28-11-2020
JE


29-11-20
AE


28/11/20
EE


9/1/2021
Signature
(Name of inspector)

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road					
Gulpara Nys-					
Nagar Khushn					
Agency: -					
Head: - FDR					
Actual length of Road: 17.50 km					
Flood affected Length: 0.900 km					
(1) providing and laying Distribution of Brick Bats on affected Road portion as per Specification					
	1 X	12 X	3.50 X	0.30 =	12.60 m ²
	1 X	45 X	3.50 X	0.45 =	70.875 m ²
	2 X	6 X	1.50 X	0.25 =	4.50 m ²
	4 X	10 X	2 X	0.25 =	20.00 m ²
	2 X	16 X	1.4 X	0.20 =	8.96 m ²

Continuation

total Qty = 116.935 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1 x	40 x	3 x	0.45	54.00 m ²
	1 x	4 x	2 x	0.15	12.00 m ²
	2 x	25 x	1.50 x	0.200	15.00 m ²
	2 x	15 x	2.00 x	0.25	15.00 m ²
	2 x	14 x	1.50 x	0.200	8.40 m ²
	4 x	5 x	2.00 x	0.300	12.00 m ²
	4 x	4 x	1.4 x	0.25	5.60 m ²
	6 x	2 x	2 x	0.30	7.20 m ²
	2 x	25 x	1.6 x	0.30	24.00 m ²
	4 x	7.0 x	2 x	0.200	11.20 m ²
(1)	2 x	8 x	1.50 x	0.20	7.20 m ²
	4 x	10 x	2 x	0.200	16.00 m ²
	4 x	10 x	1.50 x	0.30	18.00 m ²
	5 x	5 x	2 x	0.2	10.00 m ²
	4 x	4 x	2 x	0.25	8.00 m ²
	2 x	18 x	1.60 x	0.20	11.52 m ²
	6 x	3 x	2 x	0.25	9.00 m ²
	4 x	4 x	2 x	0.30	9.60 m ²
	4 x	6 x	2 x	0.25	12.00 m ²
	4 x	3 x	2 x	0.25	6.00 m ²
	4 x	3 x	2 x	0.20	4.80 m ²
	6 x	3 x	1.50 x	0.30	8.10 m ²
	4 x	3 x	2 x	0.20	4.80 m ²
	4 x	12 x	1.40 x	0.25	16.80 m ²
(1)	4 x	3 x	2 x	0.20	4.80 m ²
					Total = 426.755 m ²

Continuation

ABSTRACT COST

3

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Providing layer & distribution of Brick Bats on affected Road portion as per Specification					
Qty vide m/s					
426.75 m ³					
@ 1874.97/m ³					
RS=800152=82					
add 12% C.S. TRS=					9,6018=33
add 1% Labour CHRS=					8001=52
total RS=					904172=67
Say RS=					904173=00
17-02-2021					17-02-2021
CP					CP
17-02-2021					17-02-2021

Continuation