

F.D.R. - 20-21

Schedule XLV-Form No. 134

પોતલકાનાથ:- નિર્મલગ્રંથે મિથાંદ્રેલ, માયા,

[illegible]

_____ SUB-DIVISION

Measurement Book

4000000 15000000 4 100 54
 4149500 4 100 50 (4000000) 4000
 4 30000 400 4 100 54
 15000000 4 415 1000000 4000
 1000000 4 415 1000000 4000
 1000000 4 415 1000000 4000

10/10/18
 Executive Engineer
 WWD Works Division
 10/10/18

Sch. XLV-Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 1398

Name of Officer

Date of first entry

1.
Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement.
(These four lines are to be filled in by the measurer.)

(These four lines should be repeated at the commencement of the measurements relating to each work).

Continuation

UNDER FDR
JFK 101A (NABART)

UNDER FDR
JFK 101A (NABART)

UNDER FDR
JFK 101A (NABART)

UNDER FDR
JFK 101A (NABART)

Abstract of Cost
 P.D. 2020-21
 3

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2. Perimeter of 2 long of Brick					
bats obtained from chimney					
all complete					
as per P.P.					
Q/y 174.24 m ³ wide TMB, Pg No. 1					
W 17.331 m ³ wide TMB, Pg No. 2					
252.171 m ³ Ch. 1864.35/m ³ = h.			4,70,	136.25	
Total = h.			4,70,	36.25	
Adt: - Seginimage fees: h.			26,	806.00	
Adt: - G.P.T. @ 12% = h.			56,	416.35	
Adt: - Labour @ 1% = h.			4,	701.36	
Total = h.			5,58,	059.96	
Day = h.			5,58,	060.00	

Per
 AS (M)

Inspection Report for Flood Damage Work

Date :


1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Nirmali | Nirmali to Miya Tola via Jarauli

A. For Road

1. Damage Location/Chainage : 6 m, 95 m
2. Damage Length : 245 m
3. Nature of Damage : Due to flood
4. Datils of Restoration Works :
 - i. Manterial being used in Restoration work : Brick Bats
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller
 - iii. Procedure taken up in Restoration work : Filling
 - iv. Restored Length : 245 m

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage :
8. Datils of Restoration Works :
 - i. Manterial being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

 30.11.20
 30/11/20
 30.11.20
Signature of JE/AE/EE

 30/11/20
Signature
Executive Engineer
(Name of Inspector)
Rural Works Department
Work Division, Birpur