

SUPAUL MAHUA BELA ROAD
Schedule XLV-Form No. 134


MB No - 1437

SUPAUL DIVISION


SUPAUL SUB-DIVISION

MEASUREMENT BOOK

प्रमाणित किया गया है कि इस माप-
पुस्तक में कुल 50 (पचास) महीने द्वारा
संचालित हुआ है जो श्री रघुबीर
कुमार लाल का अग्र-प्रवेश
पुस्तक के पुस्तक से निम्नलिखित
गया है


कार्यपालक अभियन्ता
प्रमाण कार्य विभाग
मुख्य प्रमोदरा (सुपौल)
16/8/20

Reissued to Shri Birendra Singh,
J.E., Supaul


17.08.2020
AE

Sch. XLV—Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 1437

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Restoration of Road from Subaul Mahua Bela Road.					
Agency - Departmental					
Authority - E.E.RWD Subaul work Division Subaul.					
Date of Measurement:-					

1/2) laying Brick Bat - ch (9.550) km.					
1X 47 X 4.5 X 0.2 = 63.450					
ch - (3.360) km.					
1X 5X 3.4 X 0.2 = 5.100					
ch - (2.1)					
1X 14X 6.3 X 2.1 = 185.220					
ch - (2.1)					
1X 14X 6.5 X 2.1 = 191.100					
ch (400) km.					
1X 7.6 X 4.875 X 0.4 = 14.820					
ch (1.45)					
1X 10.5X 1.45 X 0.4 = 6.090					
ch (3.500) km.					
1X 13X 6X 0.4 = 31.200					

Continuation

Box No. - 4000 M. 10

Continuation

11/10/2020

11/10

11/10

11/10

11/10

11/10

11/10

Supply of Bunkers of
oil

Total (in m) = 224.00

Total (in m³) = 137.32

Sum = 137.00

Labour filling Empty

Cement bags (with loss)

Small stitching the bag

and Picking up - do -

at ch. 3.36 km

Total = 3176.0

Balance Road at

Ch - 550 km

Total = 190.0

of
23/10/2020

DE

PV
23/10/2020
P.E.

Continuation

ABSTRACT OF COST.

4

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Land filling in foundation					
Trenches as per drawing &					
Technical specification					
2) Moulding & laying of Brd					
Bals.					
Qty = 615.40 m ³ vide TmB					
lg no - (2)					
a) 1860.3 1864.35 B					1147324.09
3) Labour for cutting 52 mm					
to 75 mm dia bamboo posts					
size & making shoes &					
observing - do -					
Qty = 23500 m vide TmB					
lg no - (3)					
a) 27.90 Rs/m					6556.50
5) Labour for filling & filling					
75 mm dia bamboo in runnals					
in position of every - do -					
Qty = 260.00 m vide TmB					
lg no (5)					
a) 5.00					1300.00
6) supply of Bamboo at					
side					
Qty = 137.00 nos vide TmB					
a) = 15844					21705.96

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7) labour filling empty cement bags with local sand stitching the bags & placing including					
Qty = 33.66/see vide fig-no					
@ 3300.20					Rs 111084.73
Total (A) Amount =					Rs 128797.23
Add Cost 12%					154556.55
Add @ 1% labour cost					12879.71
(A) Total =					Rs 1455,407.48

Calculation of S.F

1. sand filling in foundation trenches per drawings & technical specification

2) Providing & laying brick-

Qty = 615.40 m³

@ 1063.00 Rs 654130.20

and

Qty = 114.44 m³

@ 141.85 Rs 16233.88

670,404.08

So,लगभग 10% 67040.00

(B) Total = 67040.00

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Total	(A)	+	(B)	=	1522447.00

g) ~~mm~~
 28/10/2020 JE
 28/10/2020 A.E.

ENT

Inspection Report for Flood Damage Work

Date : _____

1. Name of PIUs :- EE. RWD, Works Division Supaul
2. Name of Block :- Supaul
3. Name of Road :- Supaul Mahua Bela Road


A. For Road

1. Damage Location/Chainage : Ch- 2550 m, 3360 m, 3400 m, 3520 m
3700 m, 3800 m / Branch Road Ch- 400 m to 550 m
2. Damage Length : 186.6 m
3. Nature of Damage : Due to flood
4. Details of Restoration Works :
 - i. Material being used in Restoration work :- Bamboo, Bricks Bats
 - ii. Equipments/Tools being used in Restoration work :- Tractor, JCB
 - iii. Procedure taken up in Restoration work :- Filling
 - iv. Restored Length :- 186.6 m

B. For Bridge

1. Damage Location/Chainage :
2. Nature of Damage :
3. Details of Restoration Works :
 - i. Material being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

N.A


25/11/2020
JE


25.11.2020
AE


25/11/20
EE


Signature
(Name of Inspector)