

7

F. D. R. 2020-2024

MBNO-1402

Schedule XLV-Form No. 134

પોઝીટીવ નાક! - 10-2 જે મહાદાસિન છે.

44 B/ 4 (+ 210 B/ 12) DIVISION

_____ SUB-DIVISION

Measurement Book

ગાંધીજીનું જન્મદિવસ ૨/૧૦/૬૮
 નિમિત્તે જાહેર સ્થાનો પર ૫૦ (પચાસ)
 મીટર જેટલું કાચું પાણી ફાંટી દેવા
 ની જાહેરાત કરવામાં આવી છે.
 આ કાચું પાણી નિયંત્રિત રીતે
 જે નિયમો અનુસાર છે

Executive Engineer
 BVD Works Division

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1402

Name of Officer _____

Date of first entry _____

1. Explain the importance of the following factors in the development of a country:

Continuation

Abstract of cost
FDR 2020-21

2

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2. Providing & laying brick bats obtained from chimney					
— — — — — all complete job.					
at per sq.					

Qty. 290.425 m³ wide TMB, P-①

@ Rs. 1864.35/m³ = Rs. 5,41,454 = ∞

Total = Rs. 5,41,454 = ∞

Add: Bargaining Fees (+) Rs. 30,872 = ∞

Add: GST @ 12% → (+) Rs. 64,974 = ∞

Add: Labouring Cost @ 1%, (+) Rs. 5,415 = ∞

Total = Rs. 6,42,715 = ∞.

Rs.
1874101
2020

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Normali / TO2 to Mahadalit Tola


A. For Road

1. Damage Location/Chainage : Ch- 70m, 120m, 755m.
2. Damage Length : 112m
3. Nature of Damage : Due to flood
4. Datils of Restoration Works :
 - i. Manterial being used in Restoration work : Brick Bats
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller.
 - iii. Procedure taken up in Restoration work : Felling
 - iv. Restored Length : 112m

B. For Bridge

~~C. For Road~~

5. Damage Location/Chainage :
6. Damage Length : N.A
7. Nature of Damage :
8. Datils of Restoration Works :
 - i. Manterial being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

 30/11/20
Signature of JE/AE/EE

 30/11/20
Signature
(Name of Inspector)
Executive Engineer
Rural Works Department
Work Division, Birpur