

FDR 2020-21

PANCHGIACHIYA TO SAROJAKONI VIA KATHARVA TOLA
PARIKOCH TAK (NABARD) UNDER FDR.

Schedule XLV-Form No. 134

MBNO-1417

R.W.D. WORKS, DIV, SUPAVL

DIVISION

MARAVNA

SUB-DIVISION

Measurement Book

प्रमाणित किया जाता है कि इस मापी
 भूमि का क्षेत्रफल ५० (पचास) वर्ग
 फीट है, जो कि ५०० ई. सी. में
 प्रमाणित किया गया है।
 प्रमाणित किया गया है कि
 प्रमाणित किया गया है कि
 प्रमाणित किया गया है कि
 प्रमाणित किया गया है कि

प्रमाणित किया गया है कि
 प्रमाणित किया गया है कि
 प्रमाणित किया गया है कि

Sch. XLV-Form No. 134

SUPAUL DIVISION
 MARAUNA SUB-DIVISION

Measurement Book

No. 1417

Inspection Report for Flood Damage Work

Date:-

1. Name of PIUs:- EE, RWD, Works Division, Supaul.
2. Name of Block:- Maraun
3. Name of Road:- Pamehgachiyas to Sanjakhri via 12th house to 8 Ponikhet Talu

A. For Road

1. Damage Location/Chainage:- 1.60 km, 3.01 km, 3.05 km
2. Damage Length:- 35.20 M
3. Nature of Damage:-
4. Details of Restoration Works:-
 - i. Material being used in Restoration works:- Brick bats
 - ii. Equipments/Tools being used in Restoration works:- JCB, Tractor.
 - iii. Procedure taken up in Restoration works:- Repair
 - iv. Restored Length:- 35.20 m

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Detail of Restoration Works:-
 - i. Material being used in Restoration works:-
 - ii. Equipments/Tools being used in Restoration work:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

N/A


JE


AE


EE

signature


(Name of Inspector)
RWD Division, Supaul