

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

2 Name of Block :-

3 Name of Road :-

A. For Road

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :- - 0.091 Kg

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

13.11.20
JE

46
13/11/20
AE

31/1/20
EE

Signature _____

(Name of inspector)

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① N/Work: - Temporary Restoration of road from 301 school to Nikat Se Bhorewasti Tak					
② Agency -					
③ A/E -					
① supply, fitting & fixing in position of pole of Bamboo - all except					
pile - $2 \times 52 = 104.0 \text{ NO}$					
Long Runner - $3 \times 9 = 27.0 \text{ "}$					
Short Runner - $\frac{1}{2} \times 52 = 26.0 \text{ "}$					
Railing - $5 \times 3 \times 9 = 54 \text{ NO}$					
Posts - $2 \times 2 \times 13 = 52 \text{ NO}$					
Total - 263.0 NO					
Total qty: 263.0 NO					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Labour for cutting 62mm to 75mm dia Bamboo in pile. — acc. to work — 3rd					
Total pile = 5272					
= 104 No					
Graded =					
③ Labour for cutting 62mm to 75mm dia Bamboo in Boundary of boundary					

52 x 3.50 = 182.50 m				
55 x 3 = 165.00 m				
347 m				
④ supply of Nonyal orb				
Total = 40 kg.				
⑤ Boring & Fixing & Fitting				
3 Plt Bamboo in Chachan with				
20 SWS wire 100mm in				
with B.F. wire — acc. to work				
53.00 x 2.50 = 132.50 m				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Construction of embankment					
along from boundary R.H. road					
upto 1000.00 ft. 1.50 ft					
Transition to site - cut					
Contd. 500 ft. from B. road to R.H.					
1x	30.0	x 20.0	x 1.0	=	600.00
3x	30.0	x 25.0	x 1.0	=	1500.00
1x	40	x 30.0	x 1.0	=	1200.0
1x	25	x 25.0	x 1.0	=	625.0
1x	40.0	x 30.0	x 1.0	=	1200.0
1x	30	x 22.0	x 1.0	=	660.0
1x	30.0	x 30.0	x 1.0	=	900.0
1x	30.0	x 25.0	x 1.0	=	750.0
1x	35.0	x 30.0	x 1.0	=	1050
1x	25	x 25.0	x 1.0	=	625.0
1x	40	x 30.0	x 1.0	=	1200
1x	27	x 25	x 1.0	=	675.0
					10,985.0
Total =					10,985.0
② Providing & Laying of Brick bed					
from chimney with already					
grading to required construction					
50.0					
50.0	x	(1.0 + 1.0)	x 30.0	=	1100.0

Less 50.0 x (1.0 + 1.0) x 30.0 = 9.0

Bill of Materials

5

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① M/WORK - Temporary Restoration of road from school ke Nikah se Bhawadpatti Tal					
② Agoney-					
③ D/E - 20/2/21					
④ Supply, Fitting & Fixing Bamboo for pile, runner Railling etc.					
Qty = 243.0 No (A-P)					
CB-155.65/No					Rs 40,936.00
⑤ Labour for erecting 62 mm to 75 mm Bamboo for Pile					
Qty = 152.0 No (A-P)					
CB-41.75/No					Rs 6346.00
					Rs 47,282.00

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F.	47282	200
② Labour for erecting					
62mm to 75mm dia					
bamboo poles in place					
for Runners					
Qty = 152.0 Kgs (P-2)					
= 347.0 Kgs (P-2)					
③					
C.B. 5.06/100				B. 1756	200
④ supply of Nails etc.					
Qty = 40.0 Kgs (P-2)					
C.B. 27.98/100				B. 11,19	200
				B. 50,157	200
⑤ Bonding & fixing of split					
Bamboo woven sheets in					
position with 20-25g of					
75mm long nails with					
G.I. wire all complete					

Continuation

Continuation

Continuation