

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - Restoration of sand from					
Baskets check to Bludane					
pmhsy Blase sal house					
Name of Agency: - Dehshmentel					
Date of entry: - 5/11/2020					
① provide and lay RCC pipe MP3100mm					
dia. - 15.0m					
2 x 7.5m					
② provide sub base layer and spread					
brick bats - all complete					
	NO.	L	B	D	Qty.
	1	10.2	$\frac{(4.5+3)}{2}$	2.50	146.63
	1	7.5	$\frac{(2.2+3)}{2}$	1.10	22.69
	1	$\frac{10.5}{5.50}$	$\frac{(4.5+5.2)}{2}$	0.80	40.32
	1	4.50	$\frac{(4.5+6.6)}{2}$	2.20	70.18
	1	10.8	$\frac{(3+2.5)}{2}$	0.50	6.19
	1	16.80	$\frac{(4.2+5.2)}{2}$	1.10	121.05
	1	9.0	1.50	0.450	6.08
	1	26.80	$\frac{(3.5+4.1)}{2}$	0.400	40.71
	2	23.0	1.250	0.380	21.85
	1	11.40	1.50	0.350	5.99
	1	21.60	4.50	0.31	30.13

Continuation

Abstract of Q4's cost

11

Sch. XLV-Form No. 134

[illegible]

Continuation