


Date: 26.12.2020

1. Name of PIU:- EE/RWD/Barh
2. Name of Block/Road:- Athmalgola/ Ramnagar Diyan Faguli Ram MP
3. For Road:- Road to DP Pashan house
4. Damage Location/Chainage:- From KM 0.000 to KM 0.400
5. Damage Length:- 0.400 Km.
6. Nature of Damage:- Flank/shoulder of road damaged due to flood in Ganga river.
- I. Material being used in Restoration Works:- Local sand, plastic/jute cement bags
- II. Equipments/Tools being used in Restoration Works:- Tractor
- III. Procedure taken up in Restoration Works:- Laying and placing local sand fill cement bags.
- IV. Restored Length:- 0.400 Km.

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
- I. Material being used in Restoration Works:-
- II. Equipments/Tools being used in Restoration Works:-
- III. Procedure taken up in Restoration Works:-
- IV. Restored Length

N/A


26.12.2020
Name of Inspector
Executive Engineer
R.W.D, Works Division Barh Dhanapur