GENERAL ABSTRACT

Balthi musheri simon to Brahlol by

Name of Road

Bhalalpur Village to Mushari Siman PMGSY Road

District

Muzaffarpur

Block

Bochaha

Division

Muzaffarpur East-2

Length of Road (in Km)

1.300 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	18.540
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	18.540
TOTAL O	COST OF PROJECT IN LACS =	18.540

sou 18.54 Lac.

Satophar Janica)

JE

RWD

AE (NAT

RWD

Technically Approved for Ps 18.54 Lac. L Rupees eighteen Lac. Fifty four thousand only).

RWD work circle

Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Gyan Wibhakar 2 Name of Block/Road: - Balthi musheri simen to Bhahlolbur :- 0,00 km, 0.30 km, 0.500 km, 0.750 km, 0.950 km (A) For Road: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brick bet (i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: (iii) :- U.SGOKM (0.56070M Restored Length (iv) (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-(i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

(Name of Inspection)

RWD WOODS DINGS