

TO2 TO PARTKOCH (PMGISY) UNDER FDR

FDR 2020-21

Schedule XLV-Form No. 134

MB No - 1418

R.W.D., WORKS, DIV, SUPAVI **DIVISION**

MARAVNIA, **SUB-DIVISION**

Measurement Book

(6)

अमावस्य तिथा ज्ञात है जिसका माप
 कुल 50 (पचास) महीने
 का है अर्थात् 50 है जो एक
 चिक्कन मसाला कुल 50 का
 अर्थात् अमावस्य महीना के नाम से
 जाना जाता है

कार्यपालक अभियन्ता
 ग्रामीण कार्य विभाग
 कार्य प्रणाली (नियंत्रण)

Sch. XLV-Form No. 134

SUPAUL DIVISION
MARAUVA SUB-DIVISION

Measurement Book

No. 1418

Name of work

Situation of work

Agency by which work is executed

Date of measurement

No. and date of approval

Office use only: To be filled by the Engineer-in-Charge of the measurement and submitted to the Engineer-in-Charge of the Department of Public Works and Engineering

Particulars Details of actual measurement Lengths of area

Name of work Restoration

of Road from 102

to Parlock (M66)

Under RDR

Agency - Department

Authority - LL, RWD, WORK

Division, Supul

Date of measurement - 03/09/00

1) Providing and laying

Brick beds in

damage portion -

Ch-1.6014 - $1 \times 10.00 \text{ m} \times \frac{5.5 + 4.5}{2} \times 2.50 = 125.00 \text{ m}^2$

Deduction for H.P. 100mm

dia -

$1 \times 2 \times 2.50 \text{ m} = 5 \text{ m}^2$

$\frac{1}{4} \times 1.2 \times 1.2 \times 5 \text{ m} = 1.5 \text{ m}^2$

Net Qty = 119.348

2) H.P. 100mm dia

$2 \times 2.50 \text{ m} = 5.00 \text{ m}^2$

for
5/9/00
for

for
5/9/00
for

for
5/9/00
for

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Recd entry, dt- 10/10/20</u>					
1.) Sand fillup in foundation trenches					
per 217					
CH-1.601KH - 1x10.0m x 4.50m x					
1.80m = 81.00m ³					
<u>Sum</u> 10/10/20 JSK					
<u>Entry</u> 10/10/20 ABP					
<u>10/10/20</u>					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT of COST</u>					
[DR - 2000-21]					
1/1) Bombing and Laying brick bbs in damage patches — as per CH					
93- 119.348 M ³ vide TMB Page ①					
					@ Rs. 1864.35/M ³ — Rs. 222506.44
2/1) Sand filling in ditch & breach patch — as per CH					
94- 81.0 M ³ vide TMB Page ②					
					@ Rs. 554.03/M ³ — Rs. 44876.43
3/1) Providing and Laying Reinforced cement concrete pipe 14/8 1000mm dia					
5/8 x 1000mm dia					
94- 5.0 M vide TMB Page ①					
					@ Rs. 3831.00/M — Rs. 19155.00
					Total Rs. — 286537.87
Add. Seigniorage fee (CH) Rs. — 14065.47					
Add. GST @ 12% — @ 1 Rs. — 34384.54					
Add. 6 Cms @ 1% — @ 1 Rs. — 2865.38					
Total, Rs. — 337853.26					
					Say Rs. — 337853.00

Continuation

per
18/11/21
JH

per
18/11/21
AS (M)

Inspection Report for Flood Damage Work

Date:-

1. Name of PILs :- E.E, KWD, Mous, Division Sdgwd,
2. Name of Block :- Manawara
3. Name of Road :- To 2 to Panikad

A. For Road

1. Damage Location/Chainage :- 1.6014
2. Damage length :- 10M
3. Nature of Damage :- Due to flood
4. Details of Restoration Works :-
 - i. Material being used in Restoration works:- brick bats, sand filling
 - ii. Equipments/Tools being used in Restoration works :- JCB, tractor,
 - iii. Procedure taken up in Restoration works :- filling
 - iv. Restored length :- 10M

B. For Bridge

1. Damage Location/Chainage :-
 2. Damage length :-
 3. Nature of Damage :-
 4. Detail of Restoration Works :-
 - i. Material being used in Restoration works :-
 - ii. Equipments/Tools being used in Restoration work :-
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored length :-
- N.A

JE 20/11/20

AE 20/11/20

EE 20/11/20

signature

20/11/20

Executive Engineer
Ru(Maintenance & Inspection)
Work Division, Panikad