

NB No. 1399

ਪ੍ਰੋਗਰਾਮ ਨੰ. 10-2, ਏ ਫਿਲਮਾਂ ਦੇ ਨਾਮਾਂ ਦੇ
ਸ਼੍ਰੇਣੀ ਅਨੁਸਾਰ, **DIVISION**

DIVISION

SUB-DIVISION

Measurement Book

પ્રમાણિત રિપોર્ટ આપવા છે કે
 રૂ. ૫૦ (પચાસ) સહીત સેલેક્શન
 યુનિટ ની રિજનરેટર પ્રદાન
 આગળ સલાહકાર આમંત્રણ આપવા
 ની કાર્ય અગ્ર પહેલ નિર્ધારિત
 થઈ છે નિર્ધારિત રિપોર્ટ આપવા છે

Executive Engineer
 BWD Works Division
 15/8/2020

Sch. XLV-Form No. 134

_____ DIVISION
 _____ SUB-DIVISION

Measurement Book

No. 1399

1.

Name of work -

Situation of work, -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Restoration of road					
from L021 to Maya Tolo.					
(FDR year - 2020-21)					
Agency:- Departmental					
Authority:- G.E. RWD, works Division,					
Supaul					
Date of measurement:- 02.09.2020					
1. Laying Brick Bat in					
Damage portion.					
Ch. 70m					
	1	13m	4m	0.3m	15.600m ³
Ch. 692m					
	1	41m	4m	0.3m	49.200m ³
Ch. 730m					
	2	17m	0.9m	0.9m	27.540m ³
Ch. 797m					
	1	3m	2m	1m	6.000m ³
Total =					98.340m ³
<div style="display: flex; justify-content: space-between;"> <div> <p>02.09.2020</p> <p>J.E</p> </div> <div> <p><i>[Signature]</i></p> <p>02/09/20</p> <p><i>[Signature]</i></p> </div> </div>					
<div style="text-align: center;"> <p><i>[Signature]</i></p> <p>2/9</p> </div>					

Continuation

FDR 2020-21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2. Providing & laying brick bats obtained from chimney					
————— all complete					
as per E/I.					
Qty, 98.34 m ³ wide TMB, Pg. No. (1)					
@ R. 1864.35/m ³ = R. 1,83,340.00					
Total = R. 1,83,340.00					
Add: Supervision Fee = R. 10,454.00					
Add: GST @ 12% = R. 22,000.00					
Add: Labour Cost @ 1% = R. 1,833.00					
Total = R. 2,17,627.00					
<i>Per m³ (11)</i>					

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- *Nirmali / LO 21 to Miya Tola*

A. For Road

1. Damage Location/Chainage : *70 m, 692 m, 730 m, 797 m*
2. Damage Length : *74 m*
3. Nature of Damage : *Due to flood*
4. Datils of Restoration Works :
 - i. Manterial being used in Restoration work : *Brick Bats*
 - ii. Equipments/Tools being used in Restoration work : *JCB, Tractor, Roller*
 - iii. Procedure taken up in Restoration work : *Filling*
 - iv. Restored Length : *74 m*

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage : *N.A*
8. Datils of Restoration Works :
 - i. Manterial being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

J.E.
30.11.20
Signature of JE/AE/EE

AM
30/11/20
Signature
(Name of Inspector)
Rural Works Department
Work Division, *Talimungay*