

Dabharzi to Ghuran
Schedule XLV-Form No. 134

MB NO-1454

RWD SUPAUL **DIVISION**

SUPAUL **SUB-DIVISION**

MEASUREMENT BOOK

परिवार अधिनियम के अन्तर्
अनुसूचित के द्वारा 50 (चतुर्था)
तक के लिए निर्धारित है।
अ. 20/10/20 17.08.2020
अ. 20/10/20 17.08.2020
अ. 20/10/20 17.08.2020

कार्यपालक अधिकारी
आमंत्रित कार्य विभाग
कार्यपालक (सुपरीन्टेंडेंट)

17/08/20

Referred to Shri Braendra Singh,
JE Sindh
17.08.2020
A.E.

Sch. XLV—Form No. 134

DIVISION
SUB-DIVISION

Measurement Book

No. 1454

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1X	21.2X	3.26X	0.9	= 61.056
CA-2.130 km					
	1X	6.8X	2.90X	0.9	= 16.443
	Total =				618.341

Labours for cutting 62 mm to 75 mm dia bamboo piles to size and making shoes and

(C) 450 c/c 1st km = $2 \times 3.1 \times 1.25 = 2.500$
 2nd = $2 \times 2.2 \times 1.25 = 2.500$
 3rd = $2 \times 2.2 \times 1.25 = 2.500$
 4th = $2 \times 2.6 \times 1.25 = 2.500$

Total 10.00

KS 1/6) Supply of bamboo at site

Total in m = 21.00

Total in nos = 3.00

3.00

7) Labours filling empty cement bags with local sand stitching the bags and placing including supply - do -

450 mm c/c 1st km = $2 \times 3.1 \times 0.6 \times 0.9 = 6.20$

2nd km = $2 \times 2.5 \times 0.7 \times 0.8 = 5.00$

3rd km = $2 \times 2.2 \times 0.8 \times 0.7 = 4.40$

4th km = $2 \times 2.6 \times 0.5 \times 0.9 = 5.20$

Total 6.00

20/10/2020
JE

20.10.2020
AE

Continuation

ABSTRACT OF Cost

4

Sch. XLV—Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
1) Providing & laying brick				
Bed				
Qty = 618.34 m ³ vide Tmb-①				
② = 1864.85				= 1152866.73
Labour for cutting & 8 mm				
to 75 mm dia bamboo piles				
to size and making shoes				
— do —				
Qty = 10.00 m vide Tmb				
lg no — ③				
Qty = 10.00 m vide Tmb lg no ①				
④ = 277.90				Rs 277.00

6) supply of bamboo at site				
Qty = 3.00 nos vide Tmb				
lg no — ⑥				
② = 158.44				Rs 475.31
3) Labour filling empty				
cement bags with local sand				
Stitching the bags and placing				
— do —				
Qty = 6.18 m ³ vide Tmb lg no ①				
② = 3300.20				80189.46
Total = Rs 1173750.50				

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	

BF : Rs. 1178750.50

Add 6.57 @ 18% : 140850.06

Add labour @ 1% : 11787.51

1,386,338.07

* Calculation of S.F

1/2 sand filling in foundation
Themselves2/2 Providing & laying Bricks
Bart

Qty = 618.34 m

@ 1063.80

Rs. 657296.22

Labour filling empty cement

bags with local sand

stitching the bags & placed

— 100 —

Qty = 20.80 m

@ 141.85 Rs/m Rs. 2950.48

Total = Rs. 660246.75

Seigniorage for @ 10% of

Basic Amount (Rs) = 66025.00

Total Add (A+B+C) 1392863.00

Qty = 1392863.00

Continuation

of
20/10/2020
J.E.

20.10.2020
A.E.

Inspection Report for Flood Damage Work

Date : 25/11/2020

1. Name of PIUs :- E.E, RWD WORKS Division Supaul
2. Name of Block :- Supaul
3. Name of Road :- Dabhari to Ghurga

A. For Road

1. Damage Location/Chainage : Ch- 100m, 1200m, 1300m, 1400m, 1500m
1600m, 1700m, 1900m, 1800m 2000m
2100m
2. Damage Length : 389.03 m
3. Nature of Damage : Due to flood
4. Details of Restoration Works :
 - i. Material being used in Restoration work :- ECB, with sand & brick bats
 - ii. Equipments/Tools being used in Restoration work :- Tractor & JCB
 - iii. Procedure taken up in Restoration work :- filling
 - iv. Restored Length :- 389.03 m

B. For Bridge

1. Damage Location/Chainage :
2. Nature of Damage :
3. Details of Restoration Works :
 - i. Material being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

} N.A

25/11/2020
JE

25.11.2020
AE

25/11/2020
EE

25/11/2020
Signature

(Name of Inspector)

EE RWD Triumphant