

Parsauni To Bitulpur (MMSY)
Schedule XLV-Form No. 134

MMS No - 1453

Supaul

DIVISION

Supaul

SUB-DIVISION

MEASUREMENT BOOK

नमस्कार, बिप्राभात में बिद्वान
म/प/पुस्तिका में सुन 50 (4-4-4)
ममति 412 412/412 412/412 412/412
ममति 412 412/412 412/412 412/412
ममति 412 412/412 412/412 412/412
ममति 412 412/412 412/412 412/412

कार्यपालक अधिकारी
ग्रामीण कार्य विभाग
कार्य प्रमण्डल (सुपरी)

17/08/2020

Reissend to Shree Birendra
Singh, JE Supaul

17/08/2020

17.08.2020
AE

Sch. XLV—Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 1453

Name to work

Situation of work

Agency by which work is executed

Date of measurement

No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Name of work - Restoration of Road from - Pavement to Bijalpur under (M.M.R.S.)					
Agency - Departmental					
Authority - E.E.R.W.D					
Subpart					
Date of Measurement -					

1/2) laying Brick Bat					
ch - 0.100 Km					
1x1.8x1.20x0.15 =					0.324
1x0.6x0.50x0.3 =					0.162
1x1x1.00x0.3 =					0.300
1x4x1.30x0.3 =					1.360
ch - 0.200 Km					
1x6x3.00x0.2 =					5.400
ch - 0.900 Km					
1x10x3.20x0.6 =					22.200
ch - 0.400 Km					
1x12.5x2.00x0.2 =					5.000
ch - 500 Km					
1x15x0.80x0.3 =					0.360

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B	D	
Ch-0.600 Km					
	1	10.0	3.40	0.6	20.400
Ch-0.700 Km					
	1	5.4	2.80	0.25	3.780
Ch-0.900 Km					
	1	1.5	1.00	0.15	0.225
Ch-1.800 Km					
	1	11.0	4.70	0.6	31.020
Ch-1.900 Km					
	1	15.00	3.70	0.6	45.900
Ch-2.100 Km					
	1	12.0	3.60	0.9	38.880
	Total				175.91

labour filling empty cement bags with local - dol

Ch-(0.20-0.60) Km

2x40x0.6x1 = 48.00

Total 48.00.

18/10/2020
JE

18.10.2020
A-E

A-E

ABSTRACT OF Cost.

3

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

1) Sand filling in foundation
Trenches as per drawing - do -

1/2 P/V & laying of brick bats
obtained from chimney
- do -

Qty = 175.51 m³ vide

Tmb pg no - (9)

@ 1864.95 Rs/m³ = 327214.80

7) Labour filling empty
Cement bags local sand

Qty = 0.48 % vide Tmb

pg no (7)

@ 3300.20 Rs/1% Rs 1584.10

Total Rs = 328798.90

Add Rs = 328798.90

Add @ 12% G.O.S.T = 39455.87

Add labour cess 1% = 3287.99

(A) Total Rs = 371542.76

Calculation of S.F

1) P/V & laying of Brick Bat
obtained from chimney with
m/c - do -

Qty = 175.51 m³.

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
@ 1063.00 Rs/m ³ = Rs					186568.19
3/2) labour filling empty cement bags with local sand					
— d o —					
Qty = 1.63 m ³					
@ = 141.85 Rs/m ³ Rs					231.92
Total Rs					186799.19
Seignorage fee @ 10% of					
Basic Amount (B)					Rs 18680.92
Total Addl (A)+(B)					390222.25
Say					390222.00

of
03/11/2020
J.E

(PUB)
03.11.2020
A-E

Inspection Report for Flood Damage Work

Date : 25/11/20

1. Name of PIUs :- E.E RWD works Division Supaul
2. Name of Block :- Supaul
3. Name of Road :- Parsauni to Bijalpur (pmssy)

A. For Road

1. Damage Location/Chainage : ch-100m, 200m, 300m, 400m, 500m, 600m, 700m, 800m, 1800m 1900m & 2000m
2. Damage Length : 94.1 m

3. Nature of Damage : Due to flure

4. Details of Restoration Works :

- i. Material being used in Restoration work :- Bricks, Bats, ESB & Bamboo
- ii. Equipments/Tools being used in Restoration work :- Tractor, JCB
- iii. Procedure taken up in Restoration work :- Filling
- iv. Restored Length :- 94.10

B. For Bridge


1. Damage Location/Chainage :

2. Nature of Damage :

3. Details of Restoration Works :

- i. Material being used in Restoration work :
- ii. Equipments/Tools being used in Restoration work :
- iii. Procedure taken up in Restoration work :
- iv. Restored Length :

N.A


25/11/2020
JE


25.11.2020
AE


25/11/20
EE


25/11/20
Signature

(Name of Inspector)

EE RWD Toluenigang