

7

F. D. R. 2020-2024

MB NO-1402

Schedule XLV-Form No. 134

પોતાના કાગળ! - 10-2 જે મહાકવિના જેમ
૫૫ જે મહાકવિ કવિ / **DIVISION**

_____ SUB-DIVISION

Measurement Book

ગાંધીજીનું જન્મદિવસ ૨/૧૦/૬૮
 નિમિત્તે જાહેર સ્થાનો પર ૫૦ (પચાસ)
 મીટર જેટલું પાણી વહેવા દેવા
 ની આજ્ઞા આપવામાં આવી છે.
 આજે આજના રોજના રોજના
 જે નિમિત્તે જાહેર સ્થાનો પર

16/8
 Executive Engineer
 BVD Works Division
 16/8

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1402

Name of Officer _____

Date of first entry _____

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

Continuation

Abstract of cost
FDK 2020-21

2

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2. Providing & laying brick bats obtained from chimney					
----- all complete job.					
at per sq.					

Qty. 290.425 m³ wide TMB, P-①

@ Rs. 1864.35/m³ = Rs. 5,41,454 = 00

Total = Rs. 5,41,454 = 00

Add: Bargaining Fees (+) Rs. 30,872 = 00

Add: GST @ 12% → (+) Rs. 64,974 = 00

Add: Labouring Cost @ 1%, (+) Rs. 5,415 = 00

Total = Rs. 6,42,715 = 00.

Rs.
1874101
2020

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Narmali / TO2 to Mahadalit Tola


A. For Road


1. Damage Location/Chainage : Ch. 90m, 120m, 755m.
2. Damage Length : 112m
3. Nature of Damage : Due to flood
4. Details of Restoration Works :
 - i. Material being used in Restoration work : Brick Bats
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller.
 - iii. Procedure taken up in Restoration work : Felling
 - iv. Restored Length : 112m


B. For Bridge


~~C. For Road~~

5. Damage Location/Chainage :
6. Damage Length : N.A
7. Nature of Damage :
8. Details of Restoration Works :
 - i. Material being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

 30.11.20
J.E.
Signature of JE/AE/EE

 30/11/20
Signature of AE/EE

 30.11.20
Signature of JE

 30/11/20
Signature
(Name of Inspector)
Executive Engineer
Rural Works Department
Work Division, Patna