

F. D. R. - 2020-2021

MB No-1405

Schedule XLV-Form No. 134

મોસજી કુ. નામ:- હરયાદી રાંધણી નિર્માણ.

વેરાવળ આપા મહેડા ૫૫ રૂ. **DIVISION**

મહેડા રૂ.

SUB-DIVISION

Measurement Book

પ્રમાણિત થિયો યાદાદે નિ ૨૦
 માર્ચ ૨૦૧૭ ને જુલો ૨૦ (૫૫૫)
 માર્ચ ૨૦૧૭ ને જુલો ૨૦ (૫૫૫)
 જો કોઈ કિસ્સામાં કોઈ કોઈ
 કોઈ કોઈ કિસ્સામાં કોઈ કોઈ
 જો કોઈ કિસ્સામાં કોઈ કોઈ
 જો કોઈ કિસ્સામાં કોઈ કોઈ
 જો કોઈ કિસ્સામાં કોઈ કોઈ
 જો કોઈ કિસ્સામાં કોઈ કોઈ

Executive Engineer
 BWD Works Division

16/8/20

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1405

Name of Officer _____

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-					
Reformation of Road					
from Hazipur Village to Akaral					
Ghoro Bandh via Mahua					
(FDR Year - 2020-21)					
Agency -					
Departmental					
Authority - E.C. Road works Division,					
Supaul.					
Date of measurement:-					
02.09.2020					
Laying Brick at 1m					
Damage Position-					

Ch. 2049m					
	1X17mX3.5mX0.4m =				23.800m ³
	2X13mX0.6mX0.2m =				3.120m ³
	1X20mX4mX0.4m =				32.000m ³
	1X19mX3.5mX0.3m =				19.950m ³
Ch. 2435m					
	1X4mX4.25mX1.2m =				20.400m ³
	1X8mX3.5mX0.15m =				4.200m ³
	1X12mX4.25mX1.2m =				61.200m ³
Ch. 2496m					
	1X9mX2mX1.2m =				21.600m ³
	1X5mX2.3mX1.5m =				17.250m ³
Ch. 2516m					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1	4 m	2 m	-	8.00 m ²
				Total	52.00 m ²

4. Labour for fitting and fixing 75 mm dia bamboo runners in position at every vertical pole with 150 mm long rails or 38 swg G.I. wire including cost of G.I. wire or mild etc. --- with all complete Job.

N Ch 2496 m					
	3 Nos	9 m		2	27.00 m
	3 Nos	5 m		2	15.00 m
(C) Ch. 2516 m					
	3 Nos	4 m		2	12.00 m

	3 Nos	4 m		2	12.00 m
				Total	66.00 m

5. Supply of Bamboo at site.

(Bamboo piling $\times 3.0$ m + Length of Runners (m) $\div 1.25$)

+ Area of Chachary $\div 1.413$ m

($\frac{58.750}{1.25} \times 3.0$ m + 66 m + $\frac{52}{1.413}$)

141 m + 66 m + 36.80 m
= 243.80

$\therefore$ Nos of Bamboo = $\frac{243.80}{6} = 40.63$

Say = 41.00

Noe.

02.09.2020

J-E

Continuation

For 9/10

2/9

Abstract of bill -
for 2000-01

4

Sch. XLV-Form No 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
1/8. Providing & laying brick bats obtained from chimney all complete job as per E/I.					
Qty. 212.37 m ³ wide TMB P-2					
@ Rs. 1864.35/m ³ = Rs.					3,95,332.00
2/3. Labour for cutting 62 mm to 75 mm dia bamboo pile — as per E/I.					
Qty. 58.75 m wide TMB P-2					
@ Rs. 27.20/m — Rs.					1,639.00

3/4. Labour for fitting & fixing split bamboo woven chackari — as per E/I.					
Qty. 52.0 m ² wide TMB P-3					
@ Rs. 73.60/m ² = Rs.					3,827.00
4/5. Labour for fitting & fixing 75 mm bamboo surmings. — as per E/I.					
Qty. 66.0 m wide TMB P-3					
@ Rs. 5.0/m — Rs.					330.00
5/6. Supply of bamboo at filter.					
Qty. 41.0 Nos. wide TMB P-3					
@ Rs. 158.44/No. = Rs.					6,496.00
Continuation					
Qty. Total = Rs.					11,08,924.00

1874121
ABCN

Inspection Report for Flood Damage Work

Date :


1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Nirmali / Hariyahi Village to Nirmali Ghera
Bandh via Mahua.

A. For Road

1. Damage Location/Chainage : Ch. 2049 m, 2435 m, 2496 m, 2516 m.
2. Damage Length : 128 m.
3. Nature of Damage : Due to Flood
4. Datils of Restoration Works :
 - i. Manterial being used in Restoration work : Bamboo and Brick Bats
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller
 - iii. Procedure taken up in Restoration work : Filling
 - iv. Restored Length : 128 m.

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length : N.A
7. Nature of Damage :
8. Datils of Restoration Works :
 - i. Manterial being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

 30.11.20
JE
 30/11/20
JE
 30.11.20
JE

Signature of JE/AE/EE

 30/11/20
Signature

(Name of Inspector)

Executive Engineer
Rural Works Department
Work Division, Trivenigang