

⑨

F.D.R. 2020-2024

MBNO-1404

Schedule XLV-Form No. 134

સોજીવો કાગળ - 10-4 જે સીટી/બી 425
કા મ(સાવિ ગ્રામ) /

DIVISION

SUB-DIVISION

Measurement Book

understand the
the number of
of the number of
of the number of
of the number of
of the number of

Executive Engineer
BWD Works Division

19/6/87

Sch. XLV-Form No. 134

DIVISION

SUB-DIVISION

Measurement Book

No. 1464

1

Name of work -

Situation of work

Agency by which work is executed.

Date of measurement -

No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Restoration of road					
from To & Sahu Tola					
(TR-2020-14)					
Agency - Departmental					
Authority - E.E. Road works Division.					
Supaul					
Date of measurement - 02.09.2020					
1 Laying BRICK PAVEMENT IN DIAGONAL					
Partion					
Ch. 0.030 Km					25760 m
1 X 23m X 56m X 0.2m =					
Ch. 0.668 Km					19.00-
1 X 38m X (2+2.5+3) / 3					
Ch. 0.698 Km					6.00-
1 X 20m X (4.5m + 5 + 5.2) / 3					
Ch. 0.768 Km					171.50-
1 X 70m X (4.5 + 5 + 5.2) / 3					
Ch. 0.768 Km					
Above 6.16 1 X 23m / 54 + 6.61 45 / 3					196.35

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
5. Labour Filling empty cement bag with local sand, stitching the bag placing including supply of seller etc bag etc all complete job.				

Ch. 0.430 km

No of bag = 23.00

Ch. 0.891 km

No of bag = 345.00

No of bag = 363.00

No of bag = 138.00

Total No of bag = 869

Total (in + rest) = 8.69

Jh
05.10.2020

JE

Jh
05/10/20

Jh

Jh

21

MB No-1403

134

TET 425

IVISION

IVISION

Abstract of Cost

FDR 2020-21

9

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2. Providing & laying brick bats obtained from chimney					
- - - - - all complete job					
as per E/I.					
Qty. 612.207 m ³ wide TMB P-(2)					
Qty. 123.08 m ³ wide TMB P-(6)					
= 735.287 m ³					
@ Rs. 1864.35/m ³ = Rs. 13,70,832.00					
2/3. Labour for cutting 62 mm to 75 mm dia bamboo piles					
- - - - - all complete					
as per E/I.					
Qty. 248.75 m wide TMB P-(3)					
Qty. 26.25 m wide TMB P-(7)					
= 275.0 m					
@ Rs. 27.90/m → Rs. 7673.00					
3/5. Labour for fitting & fixing 75 mm dia bamboo piles					
- - - - - as per E/I.					
Qty. 327.0 m wide TMB P-(4)					
Qty. 35.0 m wide TMB P-(7)					
= 362.0 m					
@ Rs. 5.0/m → Rs. 1810.0					
					1

Continuation C/P → Rs. 13,80,315.00

slc

10

Continuation

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.

2. Name of Block/Road :- Nirmali | Toh to Sahu Tola.

A. For Road

1. Damage Location/Chainage : 30m, 668m, 698m, 800m, 832m, 919m,

2. Damage Length : 465m

3. Nature of Damage : Due to flood

4. Datils of Restoration Works :

- Manterial being used in Restoration work : Hume Pipe, Bamboo, ECB filling with Local Sand, Brick Bats.
- Equipments/Tools being used in Restoration work : JCB, Tractor, Roller
- Procedure taken up in Restoration work : Filling.
- Restored Length : 465m

B. For Bridge


5. Damage Location/Chainage :

6. Damage Length :

7. Nature of Damage :

8. Datils of Restoration Works :

- Manterial being used in Restoration work :
- Equipments/Tools being used in Restoration work :
- Procedure taken up in Restoration work :
- Restored Length :


JE/AE/EE
30.11.20
30/11/20

Signature of JE/AE/EE


Executive Engineer
Rd & Works Department
Work Division, Supaul
30/11/20