कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ

Email ID:- bhabua.rwd@gmail.com

Mob:- 8986915314

22.05-21

पत्रांक. 690

भमुआ/दिनांक.....

प्रेषक,

Lohar

कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ

सेवा में,

सचिव-सह-शक्ति प्रदत्त पदाधिकारी, BRRDA तीसरी मंजिल भूमि विकास बैंक भवन, बुद्ध मार्ग, पटना।

मुख्यमंत्री ग्राम सम्पर्क योजना (एस०सी०) मद के अंतर्गत पथ में कराये गये विषय :-कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय.

उपरोक्त विषय के संबंध में सूचित करना है कि मुख्यमंत्री ग्राम सम्पर्क योजना (एस0सी0) मद के अंतर्गत पथ में कराये गये कार्यों के विरूद्ध संवेदको को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जा रही है। अधियाचित पथों का प्रगति MIS पर अद्यतन हैं, एवं इन पथों मे कोई ATR लंबित नहीं हैं।

निम्नांकित संवेदको का नाम प्राधिकार पत्र में जोड़ने की कृपा की जाए।

1. श्री नरेन्द्र कुमार।

अनु :- यथोक्त।

विश्वासभाजन

कार्यपौर्लक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, भभुआ

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to May 23, 2021

Sl.No	Name of Scheme	Sanction No.& Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
	of Rural roads Under MMGSY (SC)	MMGSY (SC) Work, BRRDA PATNA	3927.85997	Certified that out of Rs. 3927.85997 lakh of grants-in-aid sanctioned during the years 2020-21 In favor of EE, RWD works division Bhabua a sum of Rs. 3896.08535 lacs has been utilized for the purpose of MMGSY (SC) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 31.77462 lakh remaining unutilized at the end of the period under report.
100		an and		
			i i i i i	
	p-/-			
	Total:		3927.85997	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- i. Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v. All other caudal formalities have been observed.

3. Physical Progress achieved:-

- i. Construction of Road Works.
- ii. Construction of CD works.

R.W.D, Works Division Bhabhua Executive Engineer
R.W.D, Works Division
Bhabhua

22.5.2

Rural Works Department MMGSY (SC) Allotment Requisition Format

Name of Division:- Bhabhua (Kaimur)

0.00000 33.27380
000
0.00
0.00000
0.00000
5.669
123.995 107.954
123.995
1.700
Total Amount

Executive Engineer
Rural Work's Department

Divisional Accounts Officer
Pural Work's Department
Works Division- Bhabhua (Kaimur)