

# GOVERNMENT OF BIHAR

FDR (2020-21)



बिहार सरकार

Name of Road:- Pachpakri Gurhenwa Road to Murli Purvi tola	Length- 1.175 Km
Estimated Cost- Rs.:- 4,52,600.00	Block- Dhaka

Submitted By  
Executive Engineer  
R.W.D. (W) Division Dhaka

## F.D.R (2020-21)

### तकनीकी प्रतिवेदन

पथ का नाम :- पंचपकड़ी - गुरहेनवा रोड से मुरली पूर्ण डोला

प्रखंड का नाम :- दाका

पथ की लम्बाई :- 1.175 किमी

शीर्ष :- MMCSY.


प्राक्कलित राशि :- ₹. 4,52,600.00


अनुरक्षण अवधि :- 3 वर्ष

प्रस्तुत प्राक्कलन पंचपकड़ी गुरहेनवा रोड से मुरली पूर्ण डोला में अतिवृष्टि / बाढ़ से क्षतिग्रस्त पथाशों में यातायात पुनर्स्थापन हेतु तैयार किया गया है जिसकी प्राक्कलित राशि मो0...4,52,600.00 रु0 है। प्रस्तुत प्राक्कलन सचिव ग्रामीण कार्य विभाग बिहार पटना के पत्रांक:-2254, दिनांक:-30.06.2020 के निर्देशानुसार तैयार किया गया है। पथ में अतिवृष्टि / बाढ़ के कारण क्षतिग्रस्त पथाशों में Brick Bats से भरने का प्रावधान किया गया है।

प्राक्कलन में दिये गये दर वर्तमान अनुसूचित दर के अनुरूप है।

कनीय अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रशाखा, दाका।

  
09/10/2020  
सहाय अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, दाका

  
09/10/2020  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमण्डल, दाका

Rate for Restoration work of Road from Pachpakri Gurhenwa Road to Murli Purvi  
for the year 2020-21 in Dhaka Block.

Length:- 1.175 Km

Name of Item	Unit	Quantity M <sup>3</sup>	Rate Rs.	Amount Rs.
Labour for laying dry graded jhama khoa or stone filter under Bricks pitching in slope or apron including light ramming etc..... all complete as per approved design specification and direction of E/I. (Brick Bat) CH: 1180M to 1190M $10.00 \times 5.0 + 6.50/2 \times 3.50 + 4.50 + 3.50/3$ Total = 220.42M <sup>3</sup>	M <sup>3</sup>	220.42	2053.40 2053.40	4,52,610.00 4,52,610.00
		Total	Rs.	4,52,610.00
			Say Rs.	4,52,600.00

4,52,700

I.E.

*Signature*  
09/10/2020  
A.E.

*Signature*  
09/10/2020  
E.E.

Per Facto

T.A.T/S is accorded for Rs. 4,52,700 =

(..... crore Four ..... lacs Fifty Two

..... Seven ..... hundred .....; only

*Signature*  
28/12/20  
S.E. (R.W.D.)  
works Circle  
Motihari

*Signature*  
29-12-20

# Inspection Report for Flood Damage Works:-

ate:-

1. Name of PIUs:- Executive Engineer. R.W.D. (W) Div.<sup>n</sup> Dhaka
2. Name of Block:- Dhaka
3. Name of Road :- Pachpakri Gurhenwa Road to murli Purvi Tola

## (A) For Road


1. Damage Location Chainage:-

2. Damage Length:- 10 M

3. Name of Damage:- Road damaged due to Flood.

4. Details of Restoration Work:-

- (i) Material being used in Restoration works:- Brick bats
- (ii) Equipments Tools being used in restoration works:-
- (iii) Procedure take up in restoration works:- Departmental.
- (iv) Restored Length:- 10 M

  
Executive Engineer  
R.W.D. (W) Div.<sup>n</sup>  
Raxaul