

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 1788 अनु

दलसिंहसराय/दिनांक 29/10/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय-

New Maintenance Policy 2018(MR New) योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-30.00000(Thirty Lakh Lakh Rupess)** की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-30.00000(Thirty Lakh Lakh Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजु

कार्यपालक अभियंता
ग्रामीण कार्य विभाग

कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administ native Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allowed Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
RRM/SA/DAL/19/003				1855/ 24.06.2019		MBD 02/2019-20 20.03.2020												Surface Completed
1		Sumar Maryati Panchayat Bhawan to Ramchandrapur R.E.O Road via Kushtwar Mahito house to Ramchandrapur.	32010401009		2.400	46.300	38.21946	20.4565	19-Dec-20	-	-	3864	25mm	5.10%	0.00000	0.00000	30.00000	
2		NH 103 Yogi Ashan se Khalishpur Muslim Tola Mazid Tak	10105080		0.700	27.7	24.84236	5.40100	19-Dec-20	-	-	-	-	-	0.00000	0.00000	0.00000	
3		Khalishpur Budhwairua (Sushil ji ke Ghar) Se Januarai Nadi (Madhya Vidhyalay Khalishpur Tak)	10105083		0.750	28.43	21.79351	6.85600	19-Dec-20	-	-	-	-	-	0.00000	0.00000	0.00000	
4		Khajuri se Chakradad Tak	10105089		2.500	51.44	46.54633	25.00285	19-Dec-20	-	-	3770	25mm	5.10%	37.23680	37.23680	0.00000	
					6.350	153.870	131.40166	57.71635							37.23680	37.23680	30.00000	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

[Signature]
Sr. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

[Signature]
Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto October 2021

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1373.95492	1373.95492	Certified that out of Rs-1373.95452 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1352.62628 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-21.32824 Lakh remaining unutilized at the end of period under the time of completion
		1373.95492	1373.95492	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-


- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved,

- (i) Construction of Road Works
- (ii) Construction of CD Works




Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai



Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

Name of Contactor - Al Krishna Construction Private Limited

Name of Work - Surmar Mayari Panchyat Bhawan to Ramchandra pur R.E.O Road via
Kushehwar Mahto house to Ramchandrapur.



[Signature]
19/8/22

[Signature]
19/8/22
H.E.

[Signature]
28/10/22
सर्वप्रमाणे अभिनंदन
आपला हा विचार अत्यंत योग्य
आमिनिबध्दता

Date	Time	Test No	Distance (meter)	Total distance (m)	BUMP (cm)	Speed (Km/Hr)	UI (mm/Km)	Corrected UI (mm/Km)	IRI (mm/Km)	Status	Latitude	Direction	Longitude	Direction	Remarks
13/08/21	18:43:35	12	100	100	28	2.6 Km/Hr	2800	2844	3841	G	25.732366	N	85.74657	E	Normal
13/08/21	18:44:00	12	100	200	26	14.5 Km/Hr	2600	2666	3626	G	25.732125	N	85.7458	E	Normal
13/08/21	18:44:26	12	100	300	24	13.4 Km/Hr	2400	2489	3410	G	25.732125	N	85.7458	E	Normal
13/08/21	18:45:04	12	59	359	27	9.8 Km/Hr	2700	2755	3734	G	25.733115	N	85.74364	E	Normal
13/08/21	18:45:35	12	100	459	26	11.7 Km/Hr	2600	2666	3626	G	25.733993	N	85.74404	E	Normal
13/08/21	18:46:01	12	100	559	24	13.9 Km/Hr	2400	2489	3410	G	25.734908	N	85.74414	E	Normal
13/08/21	18:46:27	12	100	659	23	13.6 Km/Hr	2300	2400	3301	G	25.735576	N	85.7444	E	Normal
13/08/21	18:46:54	12	100	759	24	13.5 Km/Hr	2400	2489	3410	G	25.735576	N	85.7444	E	Normal
13/08/21	18:47:34	12	90	849	25	9.0 Km/Hr	2500	2578	3518	G	25.737327	N	85.74476	E	Breaker
13/08/21	18:48:07	12	100	949	26	10.9 Km/Hr	2600	2666	3626	G	25.737327	N	85.74476	E	Normal
13/08/21	18:48:29	12	100	1049	23	16.3 Km/Hr	2300	2400	3301	G	25.737327	N	85.74476	E	Normal
13/08/21	18:48:45	12	100	1149	24	21.8 Km/Hr	2400	2489	3410	G	25.737327	N	85.74476	E	Normal
13/08/21	18:49:02	12	100	1249	25	21.1 Km/Hr	2500	2578	3518	G	25.738168	N	85.74275	E	Normal
13/08/21	18:49:19	12	59	1308	27	21.6 Km/Hr	2700	2755	3734	G	25.737557	N	85.74131	E	Breaker
13/08/21	18:49:37	12	100	1408	28	19.6 Km/Hr	2800	2844	3841	G	25.737557	N	85.74131	E	Normal
13/08/21	18:49:56	12	100	1508	29	19.4 Km/Hr	2900	2933	3948	G	25.737557	N	85.74131	E	Normal
13/08/21	18:50:14	12	100	1608	28	20.0 Km/Hr	2800	2844	3841	G	25.737079	N	85.7387	E	Normal
13/08/21	18:50:32	12	55	1663	24	19.8 Km/Hr	2400	2489	3410	G	25.737111	N	85.73734	E	Normal
13/08/21	18:51:02	12	100	1763	27	12.4 Km/Hr	2700	2755	3734	G	25.737134	N	85.73695	E	Normal
13/08/21	18:51:25	12	100	1863	25	15.1 Km/Hr	2500	2578	3518	G	25.737134	N	85.73695	E	Normal
13/08/21	18:51:50	12	100	1963	28	14.2 Km/Hr	2800	2844	3841	G	25.737134	N	85.73695	E	Normal
13/08/21	18:52:15	12	100	2063	26	14.8 Km/Hr	2600	2666	3626	G	25.737134	N	85.73695	E	Normal
13/08/21	18:53:17	12	100	2163	24	5.6 Km/Hr	2400	2489	3410	G	25.73768	N	85.73219	E	Normal
13/08/21	18:53:35	12	100	2263	26	20.2 Km/Hr	2600	2666	3626	G	25.737844	N	85.73159	E	Normal
13/08/21	18:53:54	12	100	2363	23	19.0 Km/Hr	2300	2400	3301	G	25.73829	N	85.7302	E	Normal
13/08/21	18:54:56	12	37	2400	22	5.7 Km/Hr	2200	2311	3191	G	25.738364	N	85.72961	E	Normal

7/9/8/21

19/8/21
AC

कर्मचारीक अभियंता
श्रीमती कर्म विभाग कर्म प्रमोदन
दलसिंहसराय