कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।

Mob No. 8986915851

Email. ID-eerwdrajauli@gmail.com

РОВ1 фікр

रजौली/दिनांक 30.10.2021

प्रेषक.

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, रजौली।

सेवा में,

नोडल पदाधिकारी,
M.R 3054,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:-

योजना मद शीर्ष (3054) अन्तर्गत नई अनुरक्षण नीती 2018 अन्तर्गत कार्य हेतु अधियचना के संबंध में।

महाशय,

उपर्युक्त विषय से संबंधित योजना मद शीर्ष 3054 अन्तर्गत नई अनुरक्षण नीती 2018 में Roh Seor- Maharwa पथ कि स्वीकृत लम्बाई 1.5 कि0 मी0 हैं पथ कि वास्तवीक लम्बाई 1.348 कि0 मी0 हैं संबंधित कार्य हेतु अधियचना विहित प्रपत्र में भरकर आवंटन उपलब्ध कराने हेतु समर्पित किया जाता हैं।

अनु०- यथोक्त

विशवास्माजन

कार्यबालक श्रामयता, ग्रामीण कार्य विभाग,

कार्य प्रमण्डल, रजौली।

制 基 排列

				F3
	-	SL NO		Name
	RM/NA/RAJ/19/0013 Roh Seor - Maharwa	Package No-		Requisition for Scheme Head:- () Name of Works Division: RWD (W) Division, Rajauli
	Roh Seor - Maharwa	Name Of Road		Requisition for Scheme Head :- MR (3054) under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
	10502702055	Project Id as Per MIS		Head :- I
	5165/25.09.2019	Administrative Approval (AA) Letter No- & Date		- MR (3054) under Bihar Rural Road M (Initial Rectification and Surface Renewal)
	1.5	Length (in km)	Admini	nder Bih
	43.13	Amount (in)	Administrative Approval (AA)	ar Rural R Surface Re
	42.521	Rectification with surface Renewal (In lakh)	Agreement Amount	oad Mai
	14.15504	Initial 5 years Rectification routine with surface Maintenance Renewal (in Lakh) lakh)	Amount	ntenance
	02MR/3054/MBD/ 2020- 21/14.03.2020	Agreement No- & Date		Policy 201
	13.12.2020	Date of Completion as per Agreement		∞ .
	t e	Actual Date of Completi		
	2595	Value or IRI (in mm/Km)		
	25	of Bitumen Layer (in mm)	Thickness	
	5.01	Bitumen content in percentage	Value of	
TOTAL 2	0	alloted Amount (in Lakh)	Previous	
Executive Trigipeer Rural Works Department Works Division-Rajauli Ruft (a) 201	0	expenditure as per MIS (in Lakh)	upto date	
Executive Engigeer Rural Works Department Works Division-Rajauli UNIV	42.521	e against work done (in takh)		
3 2	On-going	Remarks		

Scanned by CamScanner

FORM GFR 19 -A

[See Government of India's Decision (I) below Rule - 150]

Name of PIU: Rural Works Department, Works Division, Rajauli

Head: Rural Road Maintenance Policy 2018

Form of Utilization Certificate for the month of October 2021

19 1 01 18 15

A Ch alon

Is sign thing

Sureringenh

SL. No.	Name of Scheme	Sanctioned No. & Date with Amout	Amount Received	Pariculars
1	Rural Road Maintenance Policy 2018	Vide letter No. & Date	RS. 302677559	Certified that out of Rs.302677559 Of grants in aid sanctioned during the Year October 2021 in favour of RWD (W) Division, Rajauli (bihar) a sum of Rs has been utilized for the purpose of RS. 293342653 Shemes as given in the margin for which it was given in which it was sanctioned and that the balance Rs.9134906 remaining untilized at the end of the period under report


2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fultiled/are being fultiled and that I have exersed the following cheks to see that that the money was acutally utilized for the purpose for which it was sanctioned.


Kind of Checks exerclesed:

- Works have been supervised by Executive Engineer/ (i)
- m . H led li Superintending Enigneer
- Periodical inspection has been conducted by Executive Engineer/Superintending Enigneer (ii)
- Construction materials have been tested. (iii)
- Measurements have been recorded in the MBs and test check conducted by
- (iv) the Assistant Engineer/Executive Engineer **护护服务**
- All other codal formalities have been observed (v)
- 3. Physical Progress achieved
 - Construction of Road works (i)
 - Construction of CD works (ii)

RWD (W) Division Rajauli

				×.								
42	L'EL		3.5	R. T. T.	20							
	3	8	STEOL RD	3	2595.06	Average						
	-				38926	Total						
	Normal	85.653248	24.865608	6	2748	2778	10.1	100	0.036	78	10:9:0	4/7/21
	Normal *	85.653585	24.865502	6	2767	2800	0	280	0.1	78	10:8:34	4/7/21
	Speed Breaker	85.654545	24.865343	6	2511	2500	10.1	250	0.1	78	10: 7: 23	4/7/21
	Speed Breaker	85.655437 *	24.865475	9	2767	280D	10.1	280	0.1	78	10:6:13	4/7/21
	Normal	85.656413	24.865298	0	1572	1400	0	140	0.1	78	10: 5: 37	4/7/21
	Speed Breaker	85.657357	24.86524	G	3450	3600	0	360	0.1	78	10: 4: 27	4/7/21
	Normal	85.658	24,865113	G	2169	2100	10.1	210	0.1	78	10: 3: 16	4/7/23
	Normal	85.659292	24.865175	G	2767	2800	10.1	280	0.1	78	10: 2: 6	4/7/21
1005 - 0005-1009 - 0009-	Speed Breaker	85.66005	24.86562	G	1828	1700	10.1	170	0.1	78	10: 1: 0	4/7/21
Good Average Poor	Normal -	85.660975	24.865548	6	3365	3500	10.1	350	0,1	78 ~	10:0:0	4/7/23
(R) RURAL ROAD	Mormal	85.661632	24.865072	9	1657	1500	10.1	150	0.1	78	9: 59: 10	4/7/21
	Normal	85.662188	24.86498	G	2511	2500	0	250	0.1	78	9: 58: 35	4/7/21
	Normal	85.567793	24.864463	G	2511	2500	40.4	30	0.012	75	9: 29: 0	4/7/21
A = 2248	Normal	85.667658	24.864463	G	3023	3100	0	310	0.1	75	9: 29: 0	4/7/22
X = 2778	Speed Breaker	85.6667	24.864563	G	3280	3400	0	340	0.1	75	9: 28: 0	4/7/21
Y=0*X*2+0354*X+3765				ROAD	VIIV	mm/km	Rate	in mm	in km	No.		
	Event	Longitude	Latitude	CATEGOR	mm/km	OR	Speed	Bumps	Length	Section	Time	Date
		20/Rajauli-13	Batch Name - MR-N/19-20/Rajauli-13	Batch Nar				nkaj Kuma	or - Shri Pa	Name of Contractor - Shri Pankaj Kumar	Name of	
												1





Scanned by CamScanner