

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 25-11-2021		District: Muzaffarpur
Division : P.W.D. Muz. East - D		Length (km): 2.275 K.M
Name of the Road: L049-T03 N1177 Kamapur Ham To Majlish Madho Chh. Chh. (V.R. 44)		
Scheme/Programme: P.M.G.S.Y.		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT + C.C.	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Pot developed in C.C. surface & exposed aggregate in ch 50 to 100 M, 300 to 400 M, 700 to 750 M & 200 to 250 M. In B.T portion Pot developed at ch - 525 to 550 M.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
Observation Remarks:- N.A		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, K.M. Post + 200 M. Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratnesh Paswan.

Designature:- E. E


 (Signature) 25.11.2021


 25.11.2021
 A.E