



INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 25-11-2021		District: Muzaffargarh
Division : R.W.D. Muz. East - II		Length (km): 0.90 K.M.
Name of the Road: Guddu House to P.M.G. S.Y. Road.		
Scheme/Programme: G.T.S. N.Y.		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement CC.	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- C.C. Pavement surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.
c)	Condition of railings/slab/approach for Bridges	N.A.
d)	Condition of Vent Clearance	N.A.
Observation Remarks:- N.A.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, KM Bst, 200m Bst is fixed in road		
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Ratnesh Parmar
Designature:- E-E


 25-11-2021
 (Signature)


 25-11-2021
 AB