

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 25-11-2021		District: Muzaffarpur	
Division : R.W.D. Muz. East - II		Length (km): 0.552 K.M.	
Name of the Road: Hn ka Kalyan Bagmat Tadbandi to Gram Khutaria R.W.D. Muzaffarpur			
Scheme/Programme:		NABARD	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
	B.T.	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
e)	Contraction Joints provided or not (CC Pavement)	NA
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road surface is in good condition.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	NA
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C. Culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, K.M. Post & 200m Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesk Paswan.

Designature:- E-G


 25-11-2021
 (Signature)


 25-11-2021
 AF