

FIELD INSPECTION REPORT

Date of Inspection : 27/11/2021	District: East Champaran
Division : Chakia	Length (km): 1.655
Name of the Road: Dhekaha Champaran Tatabandh to Manjash	
Scheme/Programme: MAINTENANCE	MMCSY (Chen)
Package No.:	Road Id No.: 31708412025
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Remarks — Road Damaged due to flood in different stretches. Temporary restoration work done with bricks beds.

NAME:

Bindu Rajak

DESIGNATION:

Executive Engineer
R.W.D.
Regional Lab. Darbhanga.

(Signature)
27/11/21
Ramesh Prasad
27/11/21