

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27-11-2021		District: Muzaffarpur
Division : R.W.D. Muz. East-II		Length (km): 1.215 km
Name of the Road: P.M.G.S.Y. Mukhija Vadamani Keshari 8069254 Paswan		
Scheme/Programme: NABARD		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S
Observation Remarks:- H.P. culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road Furniture, Informatory Board, K.M. Post and 200m Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-
Designature:-

Ratnesh Paswan
E.E

27/11/2021
(Signature)

A/S
27/11/21
A.E