INSPECTION REPORT FOR ROUTINE MAINTENANCE

ate of	Inspection: 27-11-2021 District: Muzafford	
ivision	: R. W D MUZ. GOM - TI Length (km): 3,29 K.M	-
lame of	the Road: Burni Choule P.M.G. Sy fred to Dhula Banth	N.H57
cheme	Programme: NABABD	
l. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B. Taw C.C.	4201
a)	Condition of Surfacing	S
b)	Riding Quality	5
c)	Road Camber	<u> </u>
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	<u>S</u> S
f)	Compaction of flank/slope & raincuts if any action Remarks:- Road Surface is in good Confin	
	Carres Desainage	
2.	Cross Drainage	NIA
a)	Condition of head walls in Hume pipe culverts including its painting	N. A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	1). A
c)	Condition of railings/slab/approach for Bridges Condition of Vent Clearance	N. 17
d) Observ	ration Remarks:-	
3.	Road Furniture	
Ang awre	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observ	ration Remarks:- Road furniture, in tormatory (Soard, 18 fixed in man.	(M BELF DEVR
4.	Compliance History	
a)	Status of ATR's & any others	
Overa	ll Rating : Satisfactory (S)/ Unsatisfactory (U)	S
Name Design	of Officer:- Ratnes L Parwan nature:- G-C' (Signal	ature)