

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26/11/2021 District: East Champaran
 Division : Motihari Length (km): 3.253
 Name of the Road: L052-L023 to Agarwa
 Scheme/Programme: PMGSY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- B.T. portion damaged.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- Km & 200m stones post not found.

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) U

Name of Officer:- *E.E.*
 26/11/2021

SIA
 26/11/21
 A.E.