

Block - Bahadurganj

**INSPECTION REPORT FOR ROUTINE MAINTENANCE**


Date of Inspection : 26-11-2021		District: Kishanganj
Division : Kishanganj 1		Length (km): 2.843 BT - 2.60 CC - 0.243
Name of the Road: Bt to Kekahatti		
Scheme/Programme: PMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> Raincut found in some stretches in flank. Surface is in good position		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b>		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b>		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory

Name of Officer:- Mahesh Pat Gupta  
 Designature:- EE, RWD, Regional Lab  
 Purnea

  
 26/11/2021  
 (Signature)