

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Block - Bahadurganj

Date of Inspection : 26-11-2021		District: Kishanganj
Division : Kishanganj-1		Length (km): 2.597 BT-2.497CC-0.102
Name of the Road: L45 to Bochaghari		
Scheme/Programme: PMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	
b)	Riding Quality	
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	
Observation Remarks:- At CH 850m, About 30m length of Road washed out in flood. Temporary Restoration work done. Permanent Restoration Required. From CH 2000 to 2200 m, Shoulder damaged in flood. Temporary restoration work done. In 2017, About 300m length of Road at last Point washed out in flood. Rest length is in good position.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:- No provision of CD works.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designation:-

Mahesh Pd. Gupta.

EE, RWD, Regional Lab

Purnea

CHP
26/11/2021
(Signature)