

Block - Kishanganj

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 26-11-2021	District: Kishanganj
Division : Kishanganj-1	Length (km): 2.396 BT-1.946 PCC-0.450
Name of the Road: Bastakola to chakla	
Scheme/Programme: PMHSY (SC)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

ATCH, 1800m, About- 80m Road crust end at CH 2200m
About- 100m Shoulder of both side of Road damaged due
to flood. Temporary Restoration work done by FDR.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Mahesh Pd Gupta.
Designation:- EE, RWD, Regional Lab -
furnes.

26/11/2021
(Signature)