

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27.11.2021		District: Muzaffarpur
Division : Muzaffarpur East - 1		Length (km): 0.900
Name of the Road: Pusa Road Muraul Chowk to Sad Kpur Path		
Scheme/Programme: MR-3054		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Surface condition is not satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:- —		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Information Board & Maintenance Board not found.		
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer:- Rana Basun Kumar Singh.

Designation:- Executive Engineer, RWD, Regional Lab. Bhagalpur

EE, Muzaffarpur East 1 - Sanjayan Bishwakar.

27.11.2021
(Signature)