

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27.11.2021		District: Muzaffarpur
Division : Muzaffarpur East - 1		Length (km): 1.030
Name of the Road: Simra Bargaon Main Road to Manek Tola (Mallah Tola)		
Scheme/Programme: MMBSY(Gen)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Surface Condition is not Satisfactory		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:- —		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Information Board not written and Maintenance Board not found.		
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer:- Rana Basu Kumar Singh.

Designature:- Executive Engineer, RWD, Regional Lab. Bhagalpur.

EE, Muzaffarpur East-1 - Sri Gyan Bilshakar.

27.11.2021
(Signature)