

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 28.11.2021		District: Munzaffarpur
Division : RWD, Munz. East - II		Length (km): 1.50 K.M.
Name of the Road: Lohr-Maheshwar To Deoria Aali (UP 54)		
Scheme/Programme: P.M.G.S.Y.		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T - ICC	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- B.T surface is damaged & not developed at ch. 90 to 930 m, 1100 to 1040 m. 1320 to 1340 m. and C.C. surface is satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
Observation Remarks:- N.A		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, km. Post & 200 m Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Ratnesh Paswan
 Designature:- E.E

28/11/2021
 (Signature)

A.B.V.
 28-11-2021
 A.B.