INSPECTION REPORT FOR ROUTINE MAINTENANCE

	Inspection: 28-11-1021 District: Muzaffarpuy	<u> </u>
Divisio	n: R. W.D. Muz. East- II Length (km): 1-05 K.M. of the Road: Middle School Tanonh to their School Ta	
	of the Road: Middle School Janonh Whish School Ja e/Programme: MMGSY (GEN)	NOTE OF
Sl. No.	Parameters to be checked	Remarks (S/U)
		Remarks (5/0)
1.	Pavement B.T - CC	
a)	Condition of Surfacing	. · · · · · · · · · · · · · · · · · · ·
b)	Riding Quality	U .
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U .
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
2.	tion Remarks:- C.C. Sunface 15 rough + agreeget in Ch - 6w to 630 M, 750 to 780 M. Bt sunface satisfactory. Cross Drainage	
21	Condition of head wells in Hume pine culverts including its painting	N. M
a)	Condition of head walls in Hume pipe culverts including its painting	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges	N.A N.A
b) c) d)	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance	N.A
b) c) d)	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges	N.A N.A
b) c) d) Dbserva	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:-	N.A N.A
b) c) d) Dbservat	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:- A	NA NA
b) c) d) Dbservat	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:- A	NA NA NA
b) c) d) bservat	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance Tion Remarks:- Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained Tion Remarks:- Road furniture, Internating Board aw yw M Pill is fixed in war	NA NA NA
b) c) d) bservat 3. a) bservat	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:- A	NA NA NA

Overall Rating :	Satisfactory (S)/ Unsatisfactory (U	J) U
Name of Officer:- Rod Designature:- E-E	thesh Paswar	(Signature)
	A184/ 28-11-2021	