

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27/11/21	District: East Champaran
Division : Motihari	Length (km): 1.705
Name of the Road: L033 to Tansariya	
Scheme/Programme: MMGSY (Gen)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

EE
27/11/2021
EE.

SA
27/11/21
A.E.