INSPECTION REPORT FOR ROUTINE MAINTENANCE

	Inspection: 27/11/2021 District: East Champo	
)ivision	: Molishan . Length (km): 1.00	to Avun Pandy H
Name of	the Road: Rama Shankar Choudhary House	0
scheme	rrogramme: O// 3/9 9	Remarks (S/U)
SL No.	Parameters to be checked	SAME AS AS AS
1.	Pavement	5
a)	Condition of Surfacing	5
b)	Riding Quality	- (
c)	Road Camber	3
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	5
1)	Compaction of flank/slope & raincuts if any	5
2.	Cross Drainage Condition of head walls in Hume pipe culverts including its painting	
2.		-
2)	Condition of Abutment & Wing walls, Slab in RCC culverts	_
b)		-
C)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	L
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board Jan & 3000 stones/Pavement road markings are provided and maintained	S
Obser	vation Remarks:-	
4.	Compliance History	
a)	Status of ATR's & any others	No
Overa	Satisfactory (S)/ Unsatisfactory (U)	5
Nume	of Officer: 392 27/11/2024 27/11/21	