

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 27.11.2021		District: Muzaffarpur.
Division : Muzaffarpur East 1		Length (km): 3.594
Name of the Road: L045 - T04 to Mural Hanjan Tola.		
Scheme/Programme: PMUS		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Surface condition is satisfactory. No rain cuts.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Boman Kumar Singh

Designature:- Executive Engineer
RWD, Regional Lale, Bhagalpur

EE, Muzaffarpur East 1 - Sri Gyan Bibhakar

27.11.2021
(Signature)