

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 29.11.2021		District: Muzaffarpur
Division: Muzaffarpur East - 1		Length (km): 1.830
Name of the Road: LD59-Sakra Faid to Nardighpur		
Scheme/Programme: PMBSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any (No rain cut)	S
Observation Remarks:- Surface Condition is Satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rama Basun Kumar Singh
Designation:- Executive Engineer
R.D. Road and Lab. Bhagalpur.

EE, Muzaffarpur East I - Sri Gyan Bihokar

28.11.2021
(Signature)