

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 27-11-2021
 District: Muzaffarpur
 Division: Muzaffarpur East-1
 Length (km): 3.05
 Name of the Road: Jalandipura to I. Laha Bazar
 Scheme/Programme: New IOR

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:- Surface condition is satisfactory.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	NO ATR.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Ram Baran Kumar Singh

Designature:- Executive Engineer
 R.D. Rajend Lal Bhagatpur

EE Muzaffarpur East-1, Sd by An B. Bhakoo.

27.11.2021
 (Signature)