

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 28.11.2021

District: Muzaffarpur

Division: Muzaffarpur East-1

Length (km): 1.230

Name of the Road: Jagdishpur Bandhangan Chowk to Hanjantola Kariaona

Scheme Programme: MMSV(G)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any <i>No rain cuts</i>	S
Observation Remarks:- <i>Surface Condition is Satisfactory.</i>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No ATR.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer: *Rama Basun Kumar Singh*

Designation: *Executive Engineer*
RWD, Regional Lab. Bhagalpur.

28.11.2021
(Signature)

EE, Muzaffarpur East-1, San Gyan B. Bhakar.