

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 28.11.2021
 District: Muzaffarpur
 Division: Muzaffarpur East - 1
 Length (km): 4.941
 Name of the Road: Bhogamma Siman to Shesha tola Suronda Prasad ke Lohar tola
 Scheme/Programme: MMBSP/LRB

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	No rain cuts. S

Observation Remarks:- Surface Condition is Satisfactory.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer: Ramesh Kumar Singh
 Designation: Executive Engineer
 RWD, Regional Lab. Bhagalpur
 EE, Muzaffarpur East 1 - Sri Bryan Bithaker.

28.11.2021
 (Signature)